




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE2940</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9004047839																								
<b>Technician Name :</b>	Ravi Rajbhar		<b>Technician Mobile :</b>	8080922965																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	03-04-2021 04:14:38																						
<b>Vendor Details :</b>																									
<b>Company Name/Client Name :</b>	Anmol Prestige HSG	<b>Customer's Mobile :</b>	9004047839	<b>Name :</b>	Mishra																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
<b>Expiry Date :</b>	21-07-2021 12:00:00		<b>Type :</b>	Non-Comprehensive																					
<b>Product Name :</b>	Ppm																								
<b>Complain :</b>	CCTV																								
<b>Technician Comment :</b>	ppm done of CCTV all camera working ok camera clean recording going on in DVR 1 ( 24 day ) DVR 2 ( 18 day)																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	ppm done of CCTV all camera working ok camera clean recording going on in DVR 1 ( 24 day ) DVR 2 ( 18 day)																								
<b>Status History :</b>	<table border="1"> <thead> <tr> <th>Date Time</th> <th>Technician Name</th> <th>Status</th> <th>Remark</th> <th>Sign</th> </tr> </thead> <tbody> <tr> <td>03-04-2021 06:36:26</td> <td>Ravi Rajbhar</td> <td>Completed</td> <td>ppm done of CCTV all camera working ok camera clean recording going on in DVR 1 ( 24 day ) DVR 2 ( 18 day)</td> <td></td> </tr> <tr> <td>03-04-2021 04:15:05</td> <td>Ravi Rajbhar</td> <td>New</td> <td></td> <td>-</td> </tr> <tr> <td>03-04-2021 04:14:38</td> <td>Ravi Rajbhar</td> <td>New</td> <td></td> <td>-</td> </tr> </tbody> </table>					Date Time	Technician Name	Status	Remark	Sign	03-04-2021 06:36:26	Ravi Rajbhar	Completed	ppm done of CCTV all camera working ok camera clean recording going on in DVR 1 ( 24 day ) DVR 2 ( 18 day)		03-04-2021 04:15:05	Ravi Rajbhar	New		-	03-04-2021 04:14:38	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
03-04-2021 06:36:26	Ravi Rajbhar	Completed	ppm done of CCTV all camera working ok camera clean recording going on in DVR 1 ( 24 day ) DVR 2 ( 18 day)																						
03-04-2021 04:15:05	Ravi Rajbhar	New		-																					
03-04-2021 04:14:38	Ravi Rajbhar	New		-																					
<b>Previous Complain History :</b>	<table border="1"> <thead> <tr> <th>Date Time</th> <th>Technician Name</th> <th>Remark</th> </tr> </thead> <tbody> <tr> <td>08-08-2023 10:23:20</td> <td>Atique Salmani</td> <td>Tv nmbr 2 hdmi extender adaptor faulty so changed new adaptor working ok And 4/5 cameras of due to rack extension socet faulty so use another board working ok lobby tv from bms recrimping working ok .</td> </tr> <tr> <td>05-08-2023 02:08:47</td> <td>Ravi Rajbhar</td> <td>boundry side one camera no video issue resloved and ok working done camera side recrimping then ok working lobby tv viewing Issue resloved</td> </tr> </tbody> </table>					Date Time	Technician Name	Remark	08-08-2023 10:23:20	Atique Salmani	Tv nmbr 2 hdmi extender adaptor faulty so changed new adaptor working ok And 4/5 cameras of due to rack extension socet faulty so use another board working ok lobby tv from bms recrimping working ok .	05-08-2023 02:08:47	Ravi Rajbhar	boundry side one camera no video issue resloved and ok working done camera side recrimping then ok working lobby tv viewing Issue resloved											
Date Time	Technician Name	Remark																							
08-08-2023 10:23:20	Atique Salmani	Tv nmbr 2 hdmi extender adaptor faulty so changed new adaptor working ok And 4/5 cameras of due to rack extension socet faulty so use another board working ok lobby tv from bms recrimping working ok .																							
05-08-2023 02:08:47	Ravi Rajbhar	boundry side one camera no video issue resloved and ok working done camera side recrimping then ok working lobby tv viewing Issue resloved																							