




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE3021</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9004047839																								
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	03-05-2021 10:05:01																						
<b>Vendor Details :</b>																									
<b>Company Name/Client Name :</b>	Anmol Prestige HSG	<b>Customer's Mobile :</b>	9004047839	<b>Name :</b>	Mishra																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
<b>Expiry Date :</b>	21-07-2021 12:00:00		<b>Type :</b>	Non-Comprehensive																					
<b>Product Name :</b>	CCTV																								
<b>Complain :</b>	1 dvr off																								
<b>Technician Comment :</b>	boath Dvr viewing lobby reception and main gate working ok. there is issue from swicher now working ok.																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	boath Dvr viewing lobby reception and main gate working ok. there is issue from swicher now working ok.																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>03-05-2021 12:10:47</td><td>Atique Salmani</td><td>Completed</td><td>boath Dvr viewing lobby reception and main gate working ok. there is issue from swicher now working ok.</td><td></td></tr><tr><td>03-05-2021 10:05:18</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>03-05-2021 10:05:01</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	03-05-2021 12:10:47	Atique Salmani	Completed	boath Dvr viewing lobby reception and main gate working ok. there is issue from swicher now working ok.		03-05-2021 10:05:18	Atique Salmani	New		-	03-05-2021 10:05:01	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
03-05-2021 12:10:47	Atique Salmani	Completed	boath Dvr viewing lobby reception and main gate working ok. there is issue from swicher now working ok.																						
03-05-2021 10:05:18	Atique Salmani	New		-																					
03-05-2021 10:05:01	Atique Salmani	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>08-08-2023 10:23:20</td><td>Atique Salmani</td><td>Tv nmbr 2 hdmi extender adaptor faulty so changed new adaptor working ok And 4/5 cameras of due to rack extension socet faulty so use another board working ok lobby tv from bms recrimping working ok .</td></tr><tr><td>05-08-2023 02:08:47</td><td>Ravi Rajbhar</td><td>boundry side one camera no video issue resloved and ok working done camera side recrimping then ok working lobby tv viewing Issue resloved</td></tr></tbody></table>					Date Time	Technician Name	Remark	08-08-2023 10:23:20	Atique Salmani	Tv nmbr 2 hdmi extender adaptor faulty so changed new adaptor working ok And 4/5 cameras of due to rack extension socet faulty so use another board working ok lobby tv from bms recrimping working ok .	05-08-2023 02:08:47	Ravi Rajbhar	boundry side one camera no video issue resloved and ok working done camera side recrimping then ok working lobby tv viewing Issue resloved											
Date Time	Technician Name	Remark																							
08-08-2023 10:23:20	Atique Salmani	Tv nmbr 2 hdmi extender adaptor faulty so changed new adaptor working ok And 4/5 cameras of due to rack extension socet faulty so use another board working ok lobby tv from bms recrimping working ok .																							
05-08-2023 02:08:47	Ravi Rajbhar	boundry side one camera no video issue resloved and ok working done camera side recrimping then ok working lobby tv viewing Issue resloved																							