




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE3603</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9004047839																								
<b>Technician Name :</b>	Yogesh Desai		<b>Technician Mobile :</b>	8080922963																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	10-08-2021 10:47:11																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	Anmol Prestige HSG	Customer's Mobile :	9004047839	Name :	Mishra																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
Expiry Date :	21-07-2021 12:00:00		Type :	Non-Comprehensive																					
<b>Product Name :</b>	CCTV																								
<b>Complain :</b>	2 camera issue need and need to check recording also																								
<b>Technician Comment :</b>	Two camera issue sloved all camera working ok. gym dvr was off for many days so there is no recording of past. now we have started the dvr .																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	Two camera issue sloved all camera working ok. gym dvr was off for many days so there is no recording of past. now we have started the dvr .																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>10-08-2021 04:48:38</td><td>YogeshDesai</td><td>Completed</td><td>Two camera issue sloved all camera working ok. gym dvr was off for many days so there is no recording of past. now we have started the dvr .</td><td></td></tr><tr><td>10-08-2021 10:49:05</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr><tr><td>10-08-2021 10:47:11</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	10-08-2021 04:48:38	YogeshDesai	Completed	Two camera issue sloved all camera working ok. gym dvr was off for many days so there is no recording of past. now we have started the dvr .		10-08-2021 10:49:05	YogeshDesai	New		-	10-08-2021 10:47:11	YogeshDesai	New		-
Date Time	Technician Name	Status	Remark	Sign																					
10-08-2021 04:48:38	YogeshDesai	Completed	Two camera issue sloved all camera working ok. gym dvr was off for many days so there is no recording of past. now we have started the dvr .																						
10-08-2021 10:49:05	YogeshDesai	New		-																					
10-08-2021 10:47:11	YogeshDesai	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>08-08-2023 10:23:20</td><td>Atique Salmani</td><td>Tv nmbr 2 hdmi extender adaptor faulty so changed new adaptor working ok And 4/5 cameras of due to rack extension socet faulty so use another board working ok lobby tv from bms recrimping working ok .</td></tr><tr><td>05-08-2023 02:08:47</td><td>Ravi Rajbhar</td><td>boundry side one camera no video issue resloved and ok working done camera side recrimping then ok working lobby tv viewing Issue resloved</td></tr></tbody></table>					Date Time	Technician Name	Remark	08-08-2023 10:23:20	Atique Salmani	Tv nmbr 2 hdmi extender adaptor faulty so changed new adaptor working ok And 4/5 cameras of due to rack extension socet faulty so use another board working ok lobby tv from bms recrimping working ok .	05-08-2023 02:08:47	Ravi Rajbhar	boundry side one camera no video issue resloved and ok working done camera side recrimping then ok working lobby tv viewing Issue resloved											
Date Time	Technician Name	Remark																							
08-08-2023 10:23:20	Atique Salmani	Tv nmbr 2 hdmi extender adaptor faulty so changed new adaptor working ok And 4/5 cameras of due to rack extension socet faulty so use another board working ok lobby tv from bms recrimping working ok .																							
05-08-2023 02:08:47	Ravi Rajbhar	boundry side one camera no video issue resloved and ok working done camera side recrimping then ok working lobby tv viewing Issue resloved																							