




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE8423</b>																				
<b>Priority :</b>	Low																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	9004047839																			
<b>Technician Name :</b>	Siddhesh Chavan		<b>Technician Mobile :</b>	8080922985																
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	25-05-2023 01:27:02																	
<b>Vendor Details :</b>																				
Company Name/Client Name :	Anmol Prestige HSG	Customer's Mobile :	9004047839	Name :	Mishra															
<b>Address :</b>																				
Mumbai , , , , Maharashtra																				
<b>AMC Details :</b>																				
Expiry Date :	21-07-2021 12:00:00		Type :	Non-Comprehensive																
<b>Product Name :</b>	CCTV																			
<b>Complain :</b>	Ground lobby tv not working again issue and main gate camera recording is also stopped																			
<b>Technician Comment :</b>	Maine gate camera side recontion and camera working OK and under observation and Lobby TV extender enter change to under extender under observation																			
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>	Maine gate camera side recontion and camera working OK and under observation and Lobby TV extender enter change to under extender under observation																			
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>25-05-2023 05:21:33</td><td>Siddhesh Chavan</td><td>Completed</td><td>Maine gate camera side recontion and camera working OK and under observation and Lobby TV extender enter change to under extender under observation</td><td></td></tr><tr><td>25-05-2023 01:27:10</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	25-05-2023 05:21:33	Siddhesh Chavan	Completed	Maine gate camera side recontion and camera working OK and under observation and Lobby TV extender enter change to under extender under observation		25-05-2023 01:27:10	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																
25-05-2023 05:21:33	Siddhesh Chavan	Completed	Maine gate camera side recontion and camera working OK and under observation and Lobby TV extender enter change to under extender under observation																	
25-05-2023 01:27:10	Siddhesh Chavan	New		-																
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>09-06-2023 05:09:53</td><td>Atique Salmani</td><td>Already working ok before visit but check n swap Poe switch port camera working ok And also lobby monitor viewing issue resolved.</td></tr><tr><td>09-06-2023 10:47:05</td><td>Atique Salmani</td><td>One D4 camera issue resolved recrimping from camera end and working ok and on under observation.</td></tr></tbody></table>					Date Time	Technician Name	Remark	09-06-2023 05:09:53	Atique Salmani	Already working ok before visit but check n swap Poe switch port camera working ok And also lobby monitor viewing issue resolved.	09-06-2023 10:47:05	Atique Salmani	One D4 camera issue resolved recrimping from camera end and working ok and on under observation.						
Date Time	Technician Name	Remark																		
09-06-2023 05:09:53	Atique Salmani	Already working ok before visit but check n swap Poe switch port camera working ok And also lobby monitor viewing issue resolved.																		
09-06-2023 10:47:05	Atique Salmani	One D4 camera issue resolved recrimping from camera end and working ok and on under observation.																		