

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE8930																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9004047839																			
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																
Ticket Type :	Complain	Date & Time :	21-07-2023 11:36:12																	
Vendor Details :																				
Company Name/Client Name :	Anmol Prestige HSG	Customer's Mobile :	9004047839	Name :	Mishra															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	21-07-2021 12:00:00		Type :	Non-Comprehensive																
Product Name :	CCTV																			
Complain :	"Boundary 1 camera off issue P1 Access door issue"																			
Technician Comment :																				
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	one camera boundary issue resolved working ok lock alignment done																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>11-08-2023 07:31:27</td><td>Atique Salmani</td><td>Completed</td><td></td><td>-</td></tr><tr><td>21-07-2023 11:36:20</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	11-08-2023 07:31:27	Atique Salmani	Completed		-	21-07-2023 11:36:20	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
11-08-2023 07:31:27	Atique Salmani	Completed		-																
21-07-2023 11:36:20	Atique Salmani	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>08-08-2023 10:23:20</td><td>Atique Salmani</td><td>Tv nmbr 2 hdmi extender adaptor faulty so changed new adaptor working ok And 4/5 cameras of due to rack extension socet faulty so use another board working ok lobby tv from bms recrimping working ok .</td></tr><tr><td>05-08-2023 02:08:47</td><td>Ravi Rajbhar</td><td>boundry side one camera no video issue resloved and ok working done camera side recrimping then ok working lobby tv viewing Issue resloved</td></tr></tbody></table>					Date Time	Technician Name	Remark	08-08-2023 10:23:20	Atique Salmani	Tv nmbr 2 hdmi extender adaptor faulty so changed new adaptor working ok And 4/5 cameras of due to rack extension socet faulty so use another board working ok lobby tv from bms recrimping working ok .	05-08-2023 02:08:47	Ravi Rajbhar	boundry side one camera no video issue resloved and ok working done camera side recrimping then ok working lobby tv viewing Issue resloved						
Date Time	Technician Name	Remark																		
08-08-2023 10:23:20	Atique Salmani	Tv nmbr 2 hdmi extender adaptor faulty so changed new adaptor working ok And 4/5 cameras of due to rack extension socet faulty so use another board working ok lobby tv from bms recrimping working ok .																		
05-08-2023 02:08:47	Ravi Rajbhar	boundry side one camera no video issue resloved and ok working done camera side recrimping then ok working lobby tv viewing Issue resloved																		