

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE9069																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9004047839																			
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																
Ticket Type :	Complain	Date & Time :	05-08-2023 02:08:47																	
Vendor Details :																				
Company Name/Client Name :	Anmol Prestige HSG	Customer's Mobile :	9004047839	Name :	Mishra															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	21-07-2021 12:00:00		Type :	Non-Comprehensive																
Product Name :	CCTV																			
Complain :	Boundary 2 camera off issue																			
Technician Comment :	boundry side one camera no video issue resloved and ok working done camera side recriping then ok working lobby tv viewing Issue resloved																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	boundry side one camera no video issue resloved and ok working done camera side recriping then ok working lobby tv viewing Issue resloved																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>05-08-2023 02:51:39</td><td>Ravi Rajbhar</td><td>Completed</td><td>boundry side one camera no video issue resloved and ok working done camera side recriping then ok working lobby tv viewing Issue resloved</td><td></td></tr><tr><td>05-08-2023 02:09:01</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	05-08-2023 02:51:39	Ravi Rajbhar	Completed	boundry side one camera no video issue resloved and ok working done camera side recriping then ok working lobby tv viewing Issue resloved		05-08-2023 02:09:01	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																
05-08-2023 02:51:39	Ravi Rajbhar	Completed	boundry side one camera no video issue resloved and ok working done camera side recriping then ok working lobby tv viewing Issue resloved																	
05-08-2023 02:09:01	Ravi Rajbhar	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>08-08-2023 10:23:20</td><td>Atique Salmani</td><td>Tv nmbr 2 hdmi extender adaptor faulty so changed new adaptor working ok And 4/5 cameras of due to rack extension socet faulty so use another board working ok lobby tv from bms recrimping working ok .</td></tr><tr><td>21-07-2023 11:36:12</td><td>Atique Salmani</td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	08-08-2023 10:23:20	Atique Salmani	Tv nmbr 2 hdmi extender adaptor faulty so changed new adaptor working ok And 4/5 cameras of due to rack extension socet faulty so use another board working ok lobby tv from bms recrimping working ok .	21-07-2023 11:36:12	Atique Salmani							
Date Time	Technician Name	Remark																		
08-08-2023 10:23:20	Atique Salmani	Tv nmbr 2 hdmi extender adaptor faulty so changed new adaptor working ok And 4/5 cameras of due to rack extension socet faulty so use another board working ok lobby tv from bms recrimping working ok .																		
21-07-2023 11:36:12	Atique Salmani																			