




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE9737</b>																				
<b>Priority :</b>	Low																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	9004047839																			
<b>Technician Name :</b>	Ravi Rajbhar		<b>Technician Mobile :</b>	8080922965																
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	05-10-2023 02:40:34																	
<b>Vendor Details :</b>																				
Company Name/Client Name :	Anmol Prestige HSG	Customer's Mobile :	9004047839	Name :	Mishra															
<b>Address :</b>																				
Mumbai , , , , Maharashtra																				
<b>AMC Details :</b>																				
Expiry Date :	21-07-2021 12:00:00		Type :	Non-Comprehensive																
<b>Product Name :</b>	CCTV																			
<b>Complain :</b>	D4 boundary camera off issue and lobby TV again and again off issue																			
<b>Technician Comment :</b>	boundary camera no video issue resolved and ok working done only poe switch side reconnected and lobby tv viewing issue resolved HDMI EXTENDER 60 METER INSTALL AND FAULTY TAKE TO OFFICE																			
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>	boundary camera no video issue resolved and ok working done only poe switch side reconnected and lobby tv viewing issue resolved HDMI EXTENDER 60 METER INSTALL AND FAULTY TAKE TO OFFICE																			
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>06-10-2023 01:14:33</td><td>Ravi Rajbhar</td><td>Completed</td><td>boundary camera no video issue resolved and ok working done only poe switch side reconnected and lobby tv viewing issue resolved HDMI EXTENDER 60 METER INSTALL AND FAULTY TAKE TO OFFICE</td><td></td></tr><tr><td>06-10-2023 10:02:53</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	06-10-2023 01:14:33	Ravi Rajbhar	Completed	boundary camera no video issue resolved and ok working done only poe switch side reconnected and lobby tv viewing issue resolved HDMI EXTENDER 60 METER INSTALL AND FAULTY TAKE TO OFFICE		06-10-2023 10:02:53	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																
06-10-2023 01:14:33	Ravi Rajbhar	Completed	boundary camera no video issue resolved and ok working done only poe switch side reconnected and lobby tv viewing issue resolved HDMI EXTENDER 60 METER INSTALL AND FAULTY TAKE TO OFFICE																	
06-10-2023 10:02:53	Ravi Rajbhar	New		-																
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>07-10-2023 11:19:04</td><td>Ravi Rajbhar</td><td>p2 one camera no link issue again and again resolved but camera Under observation</td></tr><tr><td>03-10-2023 10:33:39</td><td>Siddhesh Chavan</td><td>d8 camera cable disconnect and reconct cable and camera issue resoved because Poe side data not blink and lobby TV issue resoved and recapping and view working OK</td></tr></tbody></table>					Date Time	Technician Name	Remark	07-10-2023 11:19:04	Ravi Rajbhar	p2 one camera no link issue again and again resolved but camera Under observation	03-10-2023 10:33:39	Siddhesh Chavan	d8 camera cable disconnect and reconct cable and camera issue resoved because Poe side data not blink and lobby TV issue resoved and recapping and view working OK						
Date Time	Technician Name	Remark																		
07-10-2023 11:19:04	Ravi Rajbhar	p2 one camera no link issue again and again resolved but camera Under observation																		
03-10-2023 10:33:39	Siddhesh Chavan	d8 camera cable disconnect and reconct cable and camera issue resoved because Poe side data not blink and lobby TV issue resoved and recapping and view working OK																		