## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

Corries Status Do							
Service Status De	tails : VE2181						
Priority:	High						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	9223207875						
Technician Name :	Atique Salmani		Technic	cian Mobile : 8080922984			
Ticket Type :	Complain	Date & Time :	05-11-2	020 11:16:04			
Vendor Details :			•				
Company Name/Client Name :	Shoppers Stop Ltd - HO	Customer's Mobile :	922320	7875	Name :	Nandu Sir	
Address:	-	-	•				
Mumbai , , , , Ma	harashtra						
AMC Details :							
Expiry Date :	01-01-1970 05:30:00		Type:	Type:			
<b>Product Name:</b>	CCTV						
Complain:	extender issue						
Technician Comment :	usb extender installed and working ok. and nvr 5th floor recording not going on when we visit now it working and nvr 5th floor on under observation pls check day by and is there any issue then inform office comain nmbr 8080922970 .						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	usb extender installed and working ok. and nvr 5th floor recording not going on when we visit now it working and nvr 5th floor on under observation pls check day by and is there any issue then inform office comain nmbr 8080922970 .						
Status History :	Date Time	Technician Name	Status	Re	emark	Sign	
	05-11-2020 04:44:37	Atique Salmani	Completed	visit now it wor floor on under of check day by an	d nvr 5th floor loing on when we king and nvr 5th observation pls and is there any office comain	Cont	
	05-11-2020 11:16:25	Atique Salmani	New			-	
	11						

Previous Complain History:	Date Time	Technician Name	Remark	
	14-10-2020 12:34:15	Atique Salmani	changed usb Mouse extender nvr nmbr 1 and working ok and also hdmi spliter issue resolved by re-start the nvr.	
	17-09-2020 11:49:00	AnilYadav	19 camera not working because 5 th floor one poe switch adopter cable loose this complain solved. 3rd floor one poe switch replace.	