## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

Service Status De	tails: VE5223						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob.	9223207875						
Technician Name :	Atique Salmani		Technician Mobile :		8080922984		
Ticket Type:	Complain	Date & Time:	16-04-2022 11:21:23				
Vendor Details :							
Company Name/Client Name :	Shoppers Stop Ltd - HO	Customer's Mobile :	9223207875	5	Name :	Nandu Sir	
Address:							
Mumbai , , , , Ma	harashtra						
AMC Details :	_						
Expiry Date :	01-01-1970 05:30:0	00	Type:				
<b>Product Name:</b>	CCTV						
Complain:	3rd floor cafeteria fisheye camera 3 nos need to install						
Technician Comment :	2 cameras installed bone fish eye one dome with steel pole (bracket ) set angel working ok.						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	2 cameras installed bone fish eye one dome with steel pole (bracket ) set angel working ok.						
Status History :	Date Time	Technician Name	Status		Remark	Sign	
	02-06-2022 01:18:28	Atique Salmani	Completed	fish eye o	s installed bone ne dome with steel cket ) set angel kk.		
	02-06-2022 11:08:05	Atique Salmani	New			-	
	14-05-2022 09:56:55	Atique Salmani	New			-	
	16-04-2022 02:02:16	Atique Salmani	Work Pending	and angel and on ca cable and and 2 can becoz pol		(,), 70	
	16-04-2022 11:21:37	Atique Salmani	New			-	
	16-04-2022 11:21:23	Atique Salmani	New			-	

Previous Complain	Date Time	Technician Name	Remark	
History :	14-05-2022 10:02:43	Atique Salmani	7 fishe eye and one dome camera angel settings done and survey also done 3rd and 5th floor . cabling 3rd floor 240 metr approx boath floor and 3* 8 port Poe swich 14 dome ip camera required .	
	18-04-2022 10:11:40	Atique Salmani	Add 3/4 employees fingers according to shoppers employee code and checked 3/5th floor servr door lock working ok but door closer issue need to resolved by carpenter and also reinstalled new lock biomatric 3rd floor design studio .	