Vallabh Enterprises

 $\label{eq:continuous} \textbf{Regd. Office}: 401, shanti kutir, shivaji road, near thakur international school, kandivali (west) mumbai - 400067 \\ \text{Support}: | \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in}$

Service Status I	Details : VE5961								
Priority:	Low								
Created By:	Admin - Apurva Vajaria								
Complaint Mob. No. :	9223207875								
Technician Name :	Mayur Yadav			Techn	ician Mobile :	8411951301			
Ticket Type :	Complain	Date & Time	Date & Time :		6-07-2022 11:15:41				
Vendor Details	•	_							
Company Name/Client Name :	Shoppers Stop Ltd - HO	Customer's M	obile :	92232	07875	Name :	Nandu Sir		
Address:									
Mumbai , , , , N	Maharashtra								
AMC Details :									
Expiry Date :	01-01-1970 05:30	:00		Type:					
Product Name:	Ppm								
Complain:	fire								
Technician Comment :	loop cable cut in multiple places due to rework and need to check								
Complain Operator :	Desktop - Apurva Vajaria								
Remark:	loop cable cut in n	nultiple places du	ıe to rev	vork and	l need to check				
Status History :	Date Time	Technician Name	St	atus	Re	mark	Sign		
	19-07-2022 05:37:12	MayurYadav	Work Pendi		loop cable cut in due to rework an	multiple places d need to check	Cysle		
	19-07-2022 03:53:06	MayurYadav	New				-		
	18-07-2022 03:23:19	MayurYadav	Work Pendi				-		
	16-07-2022 05:37:52	MayurYadav	Comp	lleted		ig (82 detector)	52		
	16-07-2022 11:15:52	MayurYadav	New				-		
	16-07-2022 11:15:41	MayurYadav	New				-		

	Previous Complain	Date Time	Technician Name	
History:		29-07-2023 02:21:56	Ravi Rajbhar	1- 3rd floor our side ok doesn't wo

Ravi Rajbhar

29-07-2023 02:19:44

,	Remark
	1- 3rd floor main enterance biometric access divice scaner check our side ok working done but nandu sir they said sometimes it doesn't work divice 2- 5th floor it room sarver room em lock issue resloved only mainget paty propely fiting our side
	2nd floor new biometric time attendance divice install with exit switch , 12 volt power supply and bolt lock install but glass door work pending client side user - 3107 pass - 3107