




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE9805</b>																				
<b>Priority :</b>	Low																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	9223207875																			
<b>Technician Name :</b>	Pravin Jagade		<b>Technician Mobile :</b>	7262044153																
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	12-10-2023 12:31:59																	
<b>Vendor Details :</b>																				
Company Name/Client Name :	Shoppers Stop Ltd - HO	Customer's Mobile :	9223207875	Name :	Nandu Sir															
<b>Address :</b>																				
Mumbai , , , , Maharashtra																				
<b>AMC Details :</b>																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
<b>Product Name :</b>	CCTV																			
<b>Complain :</b>	all cameras not working need to check																			
<b>Technician Comment :</b>	5 th floor 15 camera not working because 1 switch off loose connection. Switch connection proper work and all camera working. And 2nd floor hikvision NVR mouse not working issue resolve working done.																			
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>	5 th floor 15 camera not working because 1 switch off loose connection. Switch connection proper work and all camera working. And 2nd floor hikvision NVR mouse not working issue resolve working done.																			
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>12-10-2023 05:32:09</td><td>PravinJagade</td><td>Completed</td><td>5 th floor 15 camera not working because 1 switch off loose connection. Switch connection proper work and all camera working. And 2nd floor hikvision NVR mouse not working issue resolve working done.</td><td></td></tr><tr><td>12-10-2023 03:54:54</td><td>PravinJagade</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	12-10-2023 05:32:09	PravinJagade	Completed	5 th floor 15 camera not working because 1 switch off loose connection. Switch connection proper work and all camera working. And 2nd floor hikvision NVR mouse not working issue resolve working done.		12-10-2023 03:54:54	PravinJagade	New		-
Date Time	Technician Name	Status	Remark	Sign																
12-10-2023 05:32:09	PravinJagade	Completed	5 th floor 15 camera not working because 1 switch off loose connection. Switch connection proper work and all camera working. And 2nd floor hikvision NVR mouse not working issue resolve working done.																	
12-10-2023 03:54:54	PravinJagade	New		-																
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>07-10-2023 10:27:52</td><td>Atique Salmani</td><td>Fire alarm pannel 5 floor healthy and third floor some above forcealing device fault All somke detector clean by blower .</td></tr><tr><td>14-09-2023 04:42:30</td><td>Atique Salmani</td><td>Second floor front side biometric issue in display also not being reset so collect for repair .</td></tr></tbody></table>					Date Time	Technician Name	Remark	07-10-2023 10:27:52	Atique Salmani	Fire alarm pannel 5 floor healthy and third floor some above forcealing device fault All somke detector clean by blower .	14-09-2023 04:42:30	Atique Salmani	Second floor front side biometric issue in display also not being reset so collect for repair .						
Date Time	Technician Name	Remark																		
07-10-2023 10:27:52	Atique Salmani	Fire alarm pannel 5 floor healthy and third floor some above forcealing device fault All somke detector clean by blower .																		
14-09-2023 04:42:30	Atique Salmani	Second floor front side biometric issue in display also not being reset so collect for repair .																		