## Vallabh Enterprises

**Regd. Office** : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE6142 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9821036391 **No. :** Technician Atique Salmani **Technician Mobile** 8080922984 Name : Complain Date & Time : 06-08-2022 05:30:54 **Ticket Type : Vendor Details :** Company Petit Tower Customer's Mobile 9821036391 Naozer Name : Name/Client CHS Ltd Baldawala Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** Intercom **Complain**: Society gym and 302 intercom issue 302 new phone installation done and also hang on wall 2501 gym cable swap issue resolved and Technician 2 cameras analog reconnection vdone but basement camera need to changed . **Comment**: Complain Desktop - Apurva Vajaria **Operator** : **Remark** : 302 new phone installation done and also hang on wall 2501 gym cable swap issue resolved and 2 cameras analog reconnection vdone but basement camera need to changed . **Status History :** Date Time **Technician Name** Status Remark Sign 08-08-2022 07:01:45 Atique Salmani Completed 302 new phone installation done and also hang on wall 2501 gym cable swap issue resolved and 2 cameras analog reconnection vdone but basement camera need to changed . Atique Salmani 08-08-2022 03:09:19 New flat no 302 intercom issue 08-08-2022 03:07:38 Atique Salmani Work Pending society gym 2501 work pending 08-08-2022 12:33:55 Atique Salmani New 06-08-2022 05:31:12 Atique Salmani New 06-08-2022 05:30:54 Atique Salmani New

Previous Complain History :	Date Time	Technician Name	Remark
	25-07-2022 10:10:38	Ravi Rajbhar	701 intercom issue resolved and ok working done port edit done 20 and new port used 64 and color cord change also difrent and 1325 cash collat
	21-07-2022 04:30:46	Siddhesh Chavan	one camera issue resolved reconnection camera side and one main gate intercom issue resolved recontion