




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE304</b>																														
<b>Priority :</b>	Low																													
<b>Created By :</b>	Admin - Apurva Vajaria																													
<b>Complaint Mob. No. :</b>	9769052914																													
<b>Technician Name :</b>	Zainul Shaikh		<b>Technician Mobile :</b>	8080922971																										
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	10-09-2019 11:38:03																											
<b>Vendor Details :</b>																														
Company Name/Client Name :	Diyas Enterprise	Customer's Mobile :	9769052914	Name :	Navin Bhai																									
<b>Address :</b>																														
Mumbai , , , , Maharashtra																														
<b>AMC Details :</b>																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
<b>Product Name :</b>	CCTV																													
<b>Complain :</b>	1 dvr not working																													
<b>Technician Comment :</b>	dvr power supply changed now online issue solved working ok																													
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																													
<b>Remark :</b>	dvr power supply changed now online issue solved working ok																													
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>27-09-2019 12:42:54</td><td>ZainulShaikh</td><td>Completed</td><td>dvr power supply changed now online issue solved working ok</td><td></td></tr><tr><td>26-09-2019 11:14:39</td><td>ZainulShaikh</td><td>New</td><td></td><td>-</td></tr><tr><td>10-09-2019 11:38:09</td><td>ZainulShaikh</td><td>New</td><td></td><td>-</td></tr><tr><td>10-09-2019 11:38:04</td><td>ZainulShaikh</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	27-09-2019 12:42:54	ZainulShaikh	Completed	dvr power supply changed now online issue solved working ok		26-09-2019 11:14:39	ZainulShaikh	New		-	10-09-2019 11:38:09	ZainulShaikh	New		-	10-09-2019 11:38:04	ZainulShaikh	New		-
Date Time	Technician Name	Status	Remark	Sign																										
27-09-2019 12:42:54	ZainulShaikh	Completed	dvr power supply changed now online issue solved working ok																											
26-09-2019 11:14:39	ZainulShaikh	New		-																										
10-09-2019 11:38:09	ZainulShaikh	New		-																										
10-09-2019 11:38:04	ZainulShaikh	New		-																										
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>10-07-2021 10:34:50</td><td>Atique Salmani</td><td>cable continuti check and after find the cable conection done and boath switch working ok supply used there was in spare suply so use its working ok.</td></tr><tr><td>30-06-2021 11:22:31</td><td>Ravi Rajbhar</td><td>intercom 4 LL line check but 204 /210 port(04/10) issue and 203and /213 line issue resolved and ok working done with cabling check</td></tr></tbody></table>					Date Time	Technician Name	Remark	10-07-2021 10:34:50	Atique Salmani	cable continuti check and after find the cable conection done and boath switch working ok supply used there was in spare suply so use its working ok.	30-06-2021 11:22:31	Ravi Rajbhar	intercom 4 LL line check but 204 /210 port(04/10) issue and 203and /213 line issue resolved and ok working done with cabling check																
Date Time	Technician Name	Remark																												
10-07-2021 10:34:50	Atique Salmani	cable continuti check and after find the cable conection done and boath switch working ok supply used there was in spare suply so use its working ok.																												
30-06-2021 11:22:31	Ravi Rajbhar	intercom 4 LL line check but 204 /210 port(04/10) issue and 203and /213 line issue resolved and ok working done with cabling check																												