Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Details : VE3346								
Priority:	Low							
Created By:	Admin - Apurva Vajaria							
Complaint Mob.	9769052914							
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965				
Ticket Type:	Call Basis	Date & Time :	30-06-2021 11:22:31					
Vendor Details :								
Company Name/Client Name :	Diyas Enterprise	Customer's Mobile :	9769052914	Name :	Navin Bhai			
Address:								
Mumbai , , , , Maharashtra								
AMC Details :								
Expiry Date :	01-01-1970 05:30:00		Type:					
Product Name:	CCTV							
Complain:	Rack installation with dvr n cable dressing							
Technician Comment :	intercom 4 LL line check but 204 /210 port(04/10) issue and 203and /213 line issue resolved and ok working done with cabling check							
Complain Operator :	Desktop - Apurva Vajaria							
Remark:	intercom 4 LL line check but 204 /210 port(04/10) issue and 203and /213 line issue resolved and ok working done with cabling check							

Status History :	Date Time	Technician Name	Status	Remark	Sign
	08-07-2021 01:28:49	Ravi Rajbhar	Completed	intercom 4 LL line check but 204 /210 port(04/10) issue and 203and /213 line issue resolved and ok working done with cabling check	Mon
	08-07-2021 10:27:28	Ravi Rajbhar	New		-
	05-07-2021 07:16:32	Ravi Rajbhar	Work Pending	2 cameras cable check and new dome cmera installed and working ok dvr SMPS changed intercom line check line coming but it's not working need programming 3/4 line painding work only intercom .old dvr on under observation.	Does
	05-07-2021 11:06:46	Ravi Rajbhar	New		-
	30-06-2021 11:22:44	Ravi Rajbhar	New		-
	30-06-2021 11:22:31	Ravi Rajbhar	New		-
Previous Complain History :	Date Time	Technician Name	nician Name Remark		
	10-07-2021 10:34:50	Atique Salmani	and boath sw	cable continuti check and after find the cable conection done and boath swich working ok supply used there was in spare suplly so use its working ok.	
	12-11-2019 03:37:50				