




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE4059</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9702786668																								
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	17-10-2021 01:55:46																						
<b>Vendor Details :</b>																									
<b>Company Name/Client Name :</b>	Beam Hospital (Womens Hospital)	<b>Customer's Mobile :</b>	9702786668	<b>Name :</b>	Nazia																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
<b>Expiry Date :</b>	30-09-2020 12:00:00		<b>Type :</b>	Comprehensive																					
<b>Product Name :</b>	Ppm																								
<b>Complain :</b>	Cctv/Access/Fire/TA																								
<b>Technician Comment :</b>	Smoke detector clean and all cameras lens clean and fire alarm pannel beeper issue and hooter and no.nc.common port issue need to changed pannel . work painding and also checklist of cameras painding. Pannel display issue keypad issue . Also changed 4 zone pannel new now only terrace hooter need to changed .																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	Smoke detector clean and all cameras lens clean and fire alarm pannel beeper issue and hooter and no.nc.common port issue need to changed pannel . work painding and also checklist of cameras painding. Pannel display issue keypad issue . Also changed 4 zone pannel new now only terrace hooter need to changed .																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>18-10-2021 05:56:03</td><td>Atique Salmani</td><td>Work Pending</td><td>Smoke detector clean and all cameras lens clean and fire alarm pannel beeper issue and hooter and no.nc.common port issue need to changed pannel . work painding and also checklist of cameras painding. Pannel display issue keypad issue . Also changed 4 zone pannel new now only terrace hooter need to changed .</td><td></td></tr><tr><td>17-10-2021 01:56:02</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>17-10-2021 01:55:47</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	18-10-2021 05:56:03	Atique Salmani	Work Pending	Smoke detector clean and all cameras lens clean and fire alarm pannel beeper issue and hooter and no.nc.common port issue need to changed pannel . work painding and also checklist of cameras painding. Pannel display issue keypad issue . Also changed 4 zone pannel new now only terrace hooter need to changed .		17-10-2021 01:56:02	Atique Salmani	New		-	17-10-2021 01:55:47	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
18-10-2021 05:56:03	Atique Salmani	Work Pending	Smoke detector clean and all cameras lens clean and fire alarm pannel beeper issue and hooter and no.nc.common port issue need to changed pannel . work painding and also checklist of cameras painding. Pannel display issue keypad issue . Also changed 4 zone pannel new now only terrace hooter need to changed .																						
17-10-2021 01:56:02	Atique Salmani	New		-																					
17-10-2021 01:55:47	Atique Salmani	New		-																					

Previous Complain History :			
	Date Time	Technician Name	Remark
	15-07-2023 10:32:24	Atique Salmani	In Manju mam phone cctv online done working ok.
	23-06-2023 10:31:29	Atique Salmani	All smok detector checked working ok also check by mcps and o.t. door access issue resolved 3rd floor 3 camera issue resolved and one smoke detector by pass by our engineer so it's need to fix in boss office in next visit boss meeting going on so painting.