




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE7209</b>																				
<b>Priority :</b>	Low																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	9702786668																			
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																
<b>Ticket Type :</b>	New Installation	<b>Date &amp; Time :</b>	28-12-2022 11:49:38																	
<b>Vendor Details :</b>																				
Company Name/Client Name :	Beam Hospital (Womens Hospital)	Customer's Mobile :	9702786668	Name :	Nazia															
<b>Address :</b>																				
Mumbai , , , , Maharashtra																				
<b>AMC Details :</b>																				
Expiry Date :	30-09-2020 12:00:00		Type :	Comprehensive																
<b>Product Name :</b>	CCTV																			
<b>Complain :</b>	1 camera outside dr rushindra s cabin( ground floor) need to change and 4 cameras on 3rd floor need to do change																			
<b>Technician Comment :</b>	5 dome cameras installation done with hdd formatted recording on . All working ok																			
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>	5 dome cameras installation done with hdd formatted recording on . All working ok																			
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>28-12-2022 07:23:58</td><td>Atique Salmani</td><td>Completed</td><td>5 dome cameras installation done with hdd formatted recording on . All working ok</td><td></td></tr><tr><td>28-12-2022 11:49:49</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	28-12-2022 07:23:58	Atique Salmani	Completed	5 dome cameras installation done with hdd formatted recording on . All working ok		28-12-2022 11:49:49	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
28-12-2022 07:23:58	Atique Salmani	Completed	5 dome cameras installation done with hdd formatted recording on . All working ok																	
28-12-2022 11:49:49	Atique Salmani	New		-																
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>21-12-2022 10:29:23</td><td>Atique Salmani</td><td>8 channel dvr 01 SMPS 08 channel.01 Hdd 01 05 / cameras dome And for viewing is same as it is according to Gajala mam Also need to plug point dvr end 4 socket by electrician.its working now vga monitor If on hdmi wants to see then hdmi cable need to lay 10 meters and also monitor need to be changed .one camera cabling need to do 7)8 meter 4+1 cable .</td></tr><tr><td>18-11-2022 11:20:27</td><td>PravinJagade</td><td>Attendance report not proper due to wrong shift setting for employees need to assign proper shift to all employees to get proper report according to shift time and also explained how to do shift setttings.</td></tr></tbody></table>					Date Time	Technician Name	Remark	21-12-2022 10:29:23	Atique Salmani	8 channel dvr 01 SMPS 08 channel.01 Hdd 01 05 / cameras dome And for viewing is same as it is according to Gajala mam Also need to plug point dvr end 4 socket by electrician.its working now vga monitor If on hdmi wants to see then hdmi cable need to lay 10 meters and also monitor need to be changed .one camera cabling need to do 7)8 meter 4+1 cable .	18-11-2022 11:20:27	PravinJagade	Attendance report not proper due to wrong shift setting for employees need to assign proper shift to all employees to get proper report according to shift time and also explained how to do shift setttings.						
Date Time	Technician Name	Remark																		
21-12-2022 10:29:23	Atique Salmani	8 channel dvr 01 SMPS 08 channel.01 Hdd 01 05 / cameras dome And for viewing is same as it is according to Gajala mam Also need to plug point dvr end 4 socket by electrician.its working now vga monitor If on hdmi wants to see then hdmi cable need to lay 10 meters and also monitor need to be changed .one camera cabling need to do 7)8 meter 4+1 cable .																		
18-11-2022 11:20:27	PravinJagade	Attendance report not proper due to wrong shift setting for employees need to assign proper shift to all employees to get proper report according to shift time and also explained how to do shift setttings.																		