

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE14943																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9324802553																			
Technician Name :	Siddhesh Chavan		Technician Mobile :	8080922985																
Ticket Type :	one_time	Date & Time :	06-06-2025 12:06:38																	
Vendor Details :																				
Company Name/Client Name :	Raheja Interface Commercial Bldg Malad	Customer's Mobile :	9324802553	Name :	Nikhil Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	Fire																			
Complain :	Bldg no 7 and 16b fire survey need to do																			
Technician Comment :																				
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	Bldg no. 7 survey done 2 MCP issue need to change and Bldg no. 16B Survey done all working 06.06.2025 - Bldg no. 16A - After conducting through review at the existing old devices connected to the newly installed fire panel we have observed continuous malfunctions and error messages the primary cause of these issues appears to be rust damage to several devices along with their nearing end of life to prevent further complications and ensure the reliability of our fire safety system we strongly recommend replacing to old devices with new ones as soon as possible 06.06.2025 - Siddhesh visited Bldg no. 11 - After conducting through review at the existing old devices connected to the newly installed fire panel we have observed continuous malfunctions and error messages the primary cause of these issues appears to be rust damage to several devices along with their nearing end of life to prevent further complications and ensure the reliability of our fire safety system 18.06.2025 - Siddhesh/Ajay visited - Bldg no. 7 fire panel check display not showing and panel cpu issue (motherboard issue) and need to change fire alarm panel																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>05-07-2025 12:27:05</td><td>Siddhesh Chavan</td><td>Completed</td><td></td><td>-</td></tr><tr><td>06-06-2025 12:06:45</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	05-07-2025 12:27:05	Siddhesh Chavan	Completed		-	06-06-2025 12:06:45	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																
05-07-2025 12:27:05	Siddhesh Chavan	Completed		-																
06-06-2025 12:06:45	Siddhesh Chavan	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>23-05-2025 11:32:40</td><td>Anil Yadav</td><td></td></tr><tr><td>10-04-2025 11:25:10</td><td>Siddhesh Chavan</td><td>26.05.2025 - Siddhesh visited - Ground floor smoke detector issue need to change near fire panel side</td></tr></tbody></table>					Date Time	Technician Name	Remark	23-05-2025 11:32:40	Anil Yadav		10-04-2025 11:25:10	Siddhesh Chavan	26.05.2025 - Siddhesh visited - Ground floor smoke detector issue need to change near fire panel side						
Date Time	Technician Name	Remark																		
23-05-2025 11:32:40	Anil Yadav																			
10-04-2025 11:25:10	Siddhesh Chavan	26.05.2025 - Siddhesh visited - Ground floor smoke detector issue need to change near fire panel side																		