




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE4106																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9967522687																								
Technician Name :	Yogesh Desai		Technician Mobile :	8080922963																					
Ticket Type :	Complain	Date & Time :	25-10-2021 12:26:48																						
Vendor Details :																									
Company Name/Client Name :	Damji Shamji - Tivon Park G&H Wing	Customer's Mobile :	9967522687	Name :	Nilesh Mane Sir																				
Address :																									
Mumbai , , , 400086 , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	CCTV																								
Complain :	gate camera issue & 1 camera of perry ferry not working																								
Technician Comment :	Main gate two camera issue sloved power cable break rejoined again camera started working again. F wing outside camera issue sloved camera side video balun was faulty. connector changed camera working ok. all camera s are working .																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	Main gate two camera issue sloved power cable break rejoined again camera started working again. F wing outside camera issue sloved camera side video balun was faulty. connector changed camera working ok. all camera s are working .																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>25-10-2021 02:30:23</td><td>YogeshDesai</td><td>Completed</td><td>Main gate two camera issue sloved power cable break rejoined again camera started working again. F wing outside camera issue sloved camera side video balun was faulty. connector changed camera working ok. all camera s are working .</td><td></td></tr><tr><td>25-10-2021 12:27:02</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr><tr><td>25-10-2021 12:26:48</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	25-10-2021 02:30:23	YogeshDesai	Completed	Main gate two camera issue sloved power cable break rejoined again camera started working again. F wing outside camera issue sloved camera side video balun was faulty. connector changed camera working ok. all camera s are working .		25-10-2021 12:27:02	YogeshDesai	New		-	25-10-2021 12:26:48	YogeshDesai	New		-
Date Time	Technician Name	Status	Remark	Sign																					
25-10-2021 02:30:23	YogeshDesai	Completed	Main gate two camera issue sloved power cable break rejoined again camera started working again. F wing outside camera issue sloved camera side video balun was faulty. connector changed camera working ok. all camera s are working .																						
25-10-2021 12:27:02	YogeshDesai	New		-																					
25-10-2021 12:26:48	YogeshDesai	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>13-02-2022 12:33:35</td><td>YogeshDesai</td><td></td></tr><tr><td>12-02-2022 06:57:13</td><td>YogeshDesai</td><td>intercom system two pin was burnt . new two pin has been installed all line working ok flat no 302, 502 , 602 . all completed.</td></tr></tbody></table>					Date Time	Technician Name	Remark	13-02-2022 12:33:35	YogeshDesai		12-02-2022 06:57:13	YogeshDesai	intercom system two pin was burnt . new two pin has been installed all line working ok flat no 302, 502 , 602 . all completed.											
Date Time	Technician Name	Remark																							
13-02-2022 12:33:35	YogeshDesai																								
12-02-2022 06:57:13	YogeshDesai	intercom system two pin was burnt . new two pin has been installed all line working ok flat no 302, 502 , 602 . all completed.																							

