

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE6038																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9967522687																								
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																					
Ticket Type :	New Installation	Date & Time :	26-07-2022 10:58:14																						
Vendor Details :																									
Company Name/Client Name :	Damji Shamji - Tivon Park F Wing	Customer's Mobile :	9967522687	Name :	Nilesh Mane Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	Intercom																								
Complain :	F-103, F-104, F-304, F-403, F-404, F-204 new intercom installation																								
Technician Comment :	f wing instrument install 103 socket removed client side phone install (bcz work progress) 104 ok 304 ok 403 ok 404 ok 204 ok																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	f wing instrument install 103 socket removed client side phone install (bcz work progress) 104 ok 304 ok 403 ok 404 ok 204 ok																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>26-07-2022 05:23:20</td><td>Ravi Rajbhar</td><td>Completed</td><td>f wing instrument install 103 socket removed client side phone install (bcz work progress) 104 ok 304 ok 403 ok 404 ok 204 ok</td><td></td></tr><tr><td>26-07-2022 10:58:33</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>26-07-2022 10:58:14</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	26-07-2022 05:23:20	Ravi Rajbhar	Completed	f wing instrument install 103 socket removed client side phone install (bcz work progress) 104 ok 304 ok 403 ok 404 ok 204 ok		26-07-2022 10:58:33	Ravi Rajbhar	New		-	26-07-2022 10:58:14	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
26-07-2022 05:23:20	Ravi Rajbhar	Completed	f wing instrument install 103 socket removed client side phone install (bcz work progress) 104 ok 304 ok 403 ok 404 ok 204 ok																						
26-07-2022 10:58:33	Ravi Rajbhar	New		-																					
26-07-2022 10:58:14	Ravi Rajbhar	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>05-07-2022 10:15:47</td><td>Atique Salmani</td><td>system was hang so it was ringing continue sonrestart and check working ok. boath wing on under observation.</td></tr><tr><td>20-04-2022 11:41:19</td><td>Atique Salmani</td><td>703 803 f wing checks and also not punch in system and also rest date and time f wing g wing pannel was off now taping on swich .</td></tr></tbody></table>					Date Time	Technician Name	Remark	05-07-2022 10:15:47	Atique Salmani	system was hang so it was ringing continue sonrestart and check working ok. boath wing on under observation.	20-04-2022 11:41:19	Atique Salmani	703 803 f wing checks and also not punch in system and also rest date and time f wing g wing pannel was off now taping on swich .											
Date Time	Technician Name	Remark																							
05-07-2022 10:15:47	Atique Salmani	system was hang so it was ringing continue sonrestart and check working ok. boath wing on under observation.																							
20-04-2022 11:41:19	Atique Salmani	703 803 f wing checks and also not punch in system and also rest date and time f wing g wing pannel was off now taping on swich .																							