

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE7894																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9967522687																			
Technician Name :	Santosh Pathak		Technician Mobile :	8080922980																
Ticket Type :	Complain	Date & Time :	16-03-2023 04:07:04																	
Vendor Details :																				
Company Name/Client Name :	Damji Shamji - Tivon Park G&H Wing	Customer's Mobile :	9967522687	Name :	Nilesh Mane Sir															
Address :																				
Mumbai , , , 400086 , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	Intercom																			
Complain :	H wing security cabin intercom issue and H-501 intercom issue																			
Technician Comment :																				
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	Kalpesh visited on 16.03.2023 - H wing security extension ok Display time set done h-501 line ok phone not connect																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>24-03-2023 03:39:50</td><td>SantoshPathak</td><td>Completed</td><td></td><td>-</td></tr><tr><td>16-03-2023 04:07:20</td><td>SantoshPathak</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	24-03-2023 03:39:50	SantoshPathak	Completed		-	16-03-2023 04:07:20	SantoshPathak	New		-
Date Time	Technician Name	Status	Remark	Sign																
24-03-2023 03:39:50	SantoshPathak	Completed		-																
16-03-2023 04:07:20	SantoshPathak	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>27-03-2023 11:34:30</td><td>Ravi Rajbhar</td><td>h wing 804 intercom issue resolved and ok working done connect to switch board sarfesh</td></tr><tr><td>17-03-2023 04:21:06</td><td>SantoshPathak</td><td>Kalpesh visited on 18.03.2023 - G wing 001 and 002 Beetel telephone installed H-103/104 beetel telephone installed, H - 201/202 - Beetel telephone installed sunil sir sign H-502 line ok telephone faulty, H-103/104 Beetel phone installed</td></tr></tbody></table>					Date Time	Technician Name	Remark	27-03-2023 11:34:30	Ravi Rajbhar	h wing 804 intercom issue resolved and ok working done connect to switch board sarfesh	17-03-2023 04:21:06	SantoshPathak	Kalpesh visited on 18.03.2023 - G wing 001 and 002 Beetel telephone installed H-103/104 beetel telephone installed, H - 201/202 - Beetel telephone installed sunil sir sign H-502 line ok telephone faulty, H-103/104 Beetel phone installed						
Date Time	Technician Name	Remark																		
27-03-2023 11:34:30	Ravi Rajbhar	h wing 804 intercom issue resolved and ok working done connect to switch board sarfesh																		
17-03-2023 04:21:06	SantoshPathak	Kalpesh visited on 18.03.2023 - G wing 001 and 002 Beetel telephone installed H-103/104 beetel telephone installed, H - 201/202 - Beetel telephone installed sunil sir sign H-502 line ok telephone faulty, H-103/104 Beetel phone installed																		