

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE8020																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	9967522687																													
Technician Name :	Santosh Pathak		Technician Mobile :	8080922980																										
Ticket Type :	Complain	Date & Time :	03-04-2023 11:03:19																											
Vendor Details :																														
Company Name/Client Name :	Damji Shamji - Tivon Park G&H Wing	Customer's Mobile :	9967522687	Name :	Nilesh Mane Sir																									
Address :																														
Mumbai , , , 400086 , Maharashtra																														
AMC Details :																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
Product Name :	CCTV																													
Complain :	g wing reception intercom issue																													
Technician Comment :																														
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	G wing security lobby extension ok																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>11-04-2023 03:37:25</td><td>SantoshPathak</td><td>Completed</td><td></td><td>-</td></tr><tr><td>04-04-2023 10:19:37</td><td>SantoshPathak</td><td>New</td><td></td><td>-</td></tr><tr><td>03-04-2023 12:51:40</td><td>SantoshPathak</td><td>New</td><td></td><td>-</td></tr><tr><td>03-04-2023 11:03:35</td><td>SantoshPathak</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	11-04-2023 03:37:25	SantoshPathak	Completed		-	04-04-2023 10:19:37	SantoshPathak	New		-	03-04-2023 12:51:40	SantoshPathak	New		-	03-04-2023 11:03:35	SantoshPathak	New		-
Date Time	Technician Name	Status	Remark	Sign																										
11-04-2023 03:37:25	SantoshPathak	Completed		-																										
04-04-2023 10:19:37	SantoshPathak	New		-																										
03-04-2023 12:51:40	SantoshPathak	New		-																										
03-04-2023 11:03:35	SantoshPathak	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>08-04-2023 04:40:47</td><td>Ravi Rajbhar</td><td>4*4 box =2 h wing change main entrance and online issue resolved user ID- tivonpark 123 password - admin@123 verification code - Admin123 and contenor side one camera blur issue resolved need to change bnc pin</td></tr><tr><td>03-04-2023 03:14:53</td><td>SantoshPathak</td><td>I ball guard 12 Volt power supply faulty 12volt power supply is damaged by overloading a new power supply will be required. 04.04.2023 - Kalpesh visited - 12V 8 ch power supply installed done 8 camera working properly sales office DVR online done</td></tr></tbody></table>					Date Time	Technician Name	Remark	08-04-2023 04:40:47	Ravi Rajbhar	4*4 box =2 h wing change main entrance and online issue resolved user ID- tivonpark 123 password - admin@123 verification code - Admin123 and contenor side one camera blur issue resolved need to change bnc pin	03-04-2023 03:14:53	SantoshPathak	I ball guard 12 Volt power supply faulty 12volt power supply is damaged by overloading a new power supply will be required. 04.04.2023 - Kalpesh visited - 12V 8 ch power supply installed done 8 camera working properly sales office DVR online done																
Date Time	Technician Name	Remark																												
08-04-2023 04:40:47	Ravi Rajbhar	4*4 box =2 h wing change main entrance and online issue resolved user ID- tivonpark 123 password - admin@123 verification code - Admin123 and contenor side one camera blur issue resolved need to change bnc pin																												
03-04-2023 03:14:53	SantoshPathak	I ball guard 12 Volt power supply faulty 12volt power supply is damaged by overloading a new power supply will be required. 04.04.2023 - Kalpesh visited - 12V 8 ch power supply installed done 8 camera working properly sales office DVR online done																												