

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE2524																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	9967522687																													
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																										
Ticket Type :	Complain	Date & Time :	04-01-2021 12:21:42																											
Vendor Details :																														
Company Name/Client Name :	Tivon Park G&H Wing	Customer's Mobile :	9967522687	Name :	Nilesh Sir																									
Address :																														
Mumbai , , , 400086 , Maharashtra																														
AMC Details :																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
Product Name :	CCTV																													
Complain :	g wing lift camera issue																													
Technician Comment :	301 . 501 . boath vdp adaptor issue need to changed. G Wing lift camera minus Disconnect form smps so reconection and working ok.																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	G Wing lift camera minus Disconnect form smps so reconection and working ok.																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>04-01-2021 03:05:08</td><td>Atique Salmani</td><td>Completed</td><td></td><td>-</td></tr><tr><td>04-01-2021 02:38:34</td><td>Atique Salmani</td><td>Awaiting Spares</td><td>301 . 501 . boath vdp adaptor issue need to changed. G Wing lift camera minus Disconnect form smps so reconection and working ok.</td><td></td></tr><tr><td>04-01-2021 12:21:56</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>04-01-2021 12:21:42</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	04-01-2021 03:05:08	Atique Salmani	Completed		-	04-01-2021 02:38:34	Atique Salmani	Awaiting Spares	301 . 501 . boath vdp adaptor issue need to changed. G Wing lift camera minus Disconnect form smps so reconection and working ok.		04-01-2021 12:21:56	Atique Salmani	New		-	04-01-2021 12:21:42	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																										
04-01-2021 03:05:08	Atique Salmani	Completed		-																										
04-01-2021 02:38:34	Atique Salmani	Awaiting Spares	301 . 501 . boath vdp adaptor issue need to changed. G Wing lift camera minus Disconnect form smps so reconection and working ok.																											
04-01-2021 12:21:56	Atique Salmani	New		-																										
04-01-2021 12:21:42	Atique Salmani	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>12-07-2023 10:48:56</td><td>Kalpesh SubhashGurav</td><td>G/601 - Telephone Dialing Mode Issue Solved Working Done.</td></tr><tr><td>05-07-2023 12:53:02</td><td>PravinJagade</td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	12-07-2023 10:48:56	Kalpesh SubhashGurav	G/601 - Telephone Dialing Mode Issue Solved Working Done.	05-07-2023 12:53:02	PravinJagade																	
Date Time	Technician Name	Remark																												
12-07-2023 10:48:56	Kalpesh SubhashGurav	G/601 - Telephone Dialing Mode Issue Solved Working Done.																												
05-07-2023 12:53:02	PravinJagade																													