


Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE6820					
Priority :	Low				
Created By :	Admin - Apurva Vajaria				
Complaint Mob. No. :	9967522687				
Technician Name :	Sonu Kumar		Technician Mobile :	8454016444	
Ticket Type :	Complain	Date & Time :	12-11-2022 10:35:21		
Vendor Details :					
Company Name/Client Name :	Tivon Park G&H Wing	Customer's Mobile :	9967522687	Name :	Nilesh Sir
Address :					
Mumbai , , , 400086 , Maharashtra					
AMC Details :					
Expiry Date :	01-01-1970 05:30:00		Type :		
Product Name :	CCTV				
Complain :	"Sales office beep sound issue and F wing tv hdmi cable need to send H-602 no tone issue, G-103 intercom calling issue , H-401 intercom calling issue, G-201 intercom calling issue, f-303 intercom calling issue				
Technician Comment :	h_wing.sales office dvr beep sound issue resolved working ok and cmaera no 81. h_wing.sales office dvr beep sound issue resolved working ok and cmaera no 8 blr video ballon chenge working ok and flat no .602 intercom line ok instrument issue and flat no. 2. F_wing. 20 mtr hdmi cable dvr to monitor is required (pending) and in flat no .303 intercom allready working ok fine. 3.G_wing. flat no. 103 intercom all ready working ok and flat no. (201 line issue not resolved) and flat no.401 intercom working ok 4.E_wing .intercom only ringing and not ringing any flat				
Complain Operator :	Desktop - Apurva Vajaria				
Remark :	h_wing.sales office dvr beep sound issue resolved working ok and cmaera no 81. h_wing.sales office dvr beep sound issue resolved working ok and cmaera no 8 blr video ballon chenge working ok and flat no .602 intercom line ok instrument issue and flat no. 2. F_wing. 20 mtr hdmi cable dvr to monitor is required (pending) and in flat no .303 intercom allready working ok fine. 3.G_wing. flat no. 103 intercom all ready working ok and flat no. (201 line issue not resolved) and flat no.401 intercom working ok 4.E_wing .intercom only ringing and not ringing any flat				

Status History :					
	Date Time	Technician Name	Status	Remark	Sign
	12-11-2022 02:28:40	Sonu Kumar	Work Pending	h_wing.sales office dvr beep sound issue resolved working ok and cmaera no 81. h_wing.sales office dvr beep sound issue resolved working ok and cmaera no 8 blr video ballon chenge working ok and flat no .602 intercom line ok instrument issue and flat no. 2. F_wing. 20 mtr hdmi cable dvr to moniter is required (pending) and in flat no .303 intercom allready working ok fine. 3.G_wing. flat no. 103 intercom all ready working ok and flat no. (201 line issue not resolved) and flat no.401 intercom working ok 4.E_wing .intercom only ringing and not ringing any flat	
	12-11-2022 10:36:43	Sonu Kumar	New		-
Previous Complain History :					
	Date Time	Technician Name	Remark		
	12-07-2023 10:48:56	Kalpesh SubhashGurav	G/601 - Telephone Dialing Mode Issue Solved Working Done.		
	05-07-2023 12:53:02	PravinJagade			