

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE7031																																								
Priority :	Low																																							
Created By :	Admin - Apurva Vajaria																																							
Complaint Mob. No. :	9967522687																																							
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																																				
Ticket Type :	Complain	Date & Time :	07-12-2022 10:05:41																																					
Vendor Details :																																								
Company Name/Client Name :	Tivon Park G&H Wing	Customer's Mobile :	9967522687	Name :	Nilesh Sir																																			
Address :																																								
Mumbai , , , 400086 , Maharashtra																																								
AMC Details :																																								
Expiry Date :	01-01-1970 05:30:00		Type :																																					
Product Name :	Intercom																																							
Complain :	G-201-Phone dead issue																																							
Technician Comment :	H wing 704 Intercom line ok but not install instrument bcz not install socket Vdp work pending bcz out door camera connector missing																																							
Complain Operator :	Desktop - Apurva Vajaria																																							
Remark :	H wing 704 Intercom line ok but not install instrument bcz not install socket Vdp work pending bcz out door camera connector missing																																							
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>10-01-2023 02:15:09</td><td>Ravi Rajbhar</td><td>Client Side</td><td>H wing 704 Intercom line ok but not install instrument bcz not install socket Vdp work pending bcz out door camera connector missing</td><td></td></tr><tr><td>10-01-2023 01:40:04</td><td>Ravi Rajbhar</td><td>Completed</td><td>201 intercom issue resolved and ok working done Cable change client side our side only connecting</td><td></td></tr><tr><td>10-01-2023 01:36:41</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>10-01-2023 11:51:38</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>07-12-2022 10:13:14</td><td>Ravi Rajbhar</td><td>Work Pending</td><td>g wing 201 cable cut duct side infrom to client line ok duct tak</td><td></td></tr><tr><td>07-12-2022 10:05:49</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	10-01-2023 02:15:09	Ravi Rajbhar	Client Side	H wing 704 Intercom line ok but not install instrument bcz not install socket Vdp work pending bcz out door camera connector missing		10-01-2023 01:40:04	Ravi Rajbhar	Completed	201 intercom issue resolved and ok working done Cable change client side our side only connecting		10-01-2023 01:36:41	Ravi Rajbhar	New		-	10-01-2023 11:51:38	Ravi Rajbhar	New		-	07-12-2022 10:13:14	Ravi Rajbhar	Work Pending	g wing 201 cable cut duct side infrom to client line ok duct tak		07-12-2022 10:05:49	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																																				
10-01-2023 02:15:09	Ravi Rajbhar	Client Side	H wing 704 Intercom line ok but not install instrument bcz not install socket Vdp work pending bcz out door camera connector missing																																					
10-01-2023 01:40:04	Ravi Rajbhar	Completed	201 intercom issue resolved and ok working done Cable change client side our side only connecting																																					
10-01-2023 01:36:41	Ravi Rajbhar	New		-																																				
10-01-2023 11:51:38	Ravi Rajbhar	New		-																																				
07-12-2022 10:13:14	Ravi Rajbhar	Work Pending	g wing 201 cable cut duct side infrom to client line ok duct tak																																					
07-12-2022 10:05:49	Ravi Rajbhar	New		-																																				

Previous Complain History :			
	Date Time	Technician Name	Remark
	12-07-2023 10:48:56	Kalpesh SubhashGurav	G/601 - Telephone Dialing Mode Issue Solved Working Done.
	05-07-2023 12:53:02	PravinJagade	