




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE9212																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9967522687																								
Technician Name :	Kalpesh Subhash Gurav		Technician Mobile :	8879684054																					
Ticket Type :	Complain	Date & Time :	19-08-2023 11:47:20																						
Vendor Details :																									
Company Name/Client Name :	Tivon Park F Wing	Customer's Mobile :	9967522687	Name :	Nilesh Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	Intercom																								
Complain :	F wing Security reception and F-01 - connection parallel so Continuous ringing issue																								
Technician Comment :	Security Display Time Set Done <input type="checkbox"/> Security and flat no.01 not a parallel connection is a separate connection. Flat no.01 lock System side ext. Working																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	Security Display Time Set Done <input type="checkbox"/> Security and flat no.01 not a parallel connection is a separate connection. Flat no.01 lock System side ext. Working																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>21-08-2023 05:20:47</td><td>Kalpesh SubhashGurav</td><td>Completed</td><td>Security Display Time Set Done <input type="checkbox"/> Security and flat no.01 not a parallel connection is a separate connection. Flat no.01 lock System side ext. Working</td><td></td></tr><tr><td>21-08-2023 03:28:47</td><td>Kalpesh SubhashGurav</td><td>New</td><td></td><td>-</td></tr><tr><td>19-08-2023 11:47:28</td><td>Kalpesh SubhashGurav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	21-08-2023 05:20:47	Kalpesh SubhashGurav	Completed	Security Display Time Set Done <input type="checkbox"/> Security and flat no.01 not a parallel connection is a separate connection. Flat no.01 lock System side ext. Working		21-08-2023 03:28:47	Kalpesh SubhashGurav	New		-	19-08-2023 11:47:28	Kalpesh SubhashGurav	New		-
Date Time	Technician Name	Status	Remark	Sign																					
21-08-2023 05:20:47	Kalpesh SubhashGurav	Completed	Security Display Time Set Done <input type="checkbox"/> Security and flat no.01 not a parallel connection is a separate connection. Flat no.01 lock System side ext. Working																						
21-08-2023 03:28:47	Kalpesh SubhashGurav	New		-																					
19-08-2023 11:47:28	Kalpesh SubhashGurav	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>10-08-2023 02:14:49</td><td>DilshadKhan</td><td></td></tr><tr><td>26-07-2023 10:43:34</td><td>InzmamUl Haq</td><td>3 camera bnc need to changed 3 camera blur issue H wing gate camera glass broken</td></tr></tbody></table>					Date Time	Technician Name	Remark	10-08-2023 02:14:49	DilshadKhan		26-07-2023 10:43:34	InzmamUl Haq	3 camera bnc need to changed 3 camera blur issue H wing gate camera glass broken											
Date Time	Technician Name	Remark																							
10-08-2023 02:14:49	DilshadKhan																								
26-07-2023 10:43:34	InzmamUl Haq	3 camera bnc need to changed 3 camera blur issue H wing gate camera glass broken																							