




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE11621																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9820042825																			
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																
Ticket Type :	Complain	Date & Time :	11-05-2024 04:38:58																	
Vendor Details :																				
Company Name/Client Name :	NEW PAKIZA SRA CHS LTD.	Customer's Mobile :	9820042825	Name :	Nimesh Bhai															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	Cannot view cameras clear on tv Some cameras color issue																			
Technician Comment :	Tv allready working 13 flor 1307 client required remooved cameras need to reinstalled as soon as possible																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	Tv allready working 13 flor 1307 client required remooved cameras need to reinstalled as soon as possible																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>13-05-2024 10:57:20</td><td>Atique Salmani</td><td>Completed</td><td>Tv allready working 13 flor 1307 client required remooved cameras need to reinstalled as soon as possible</td><td></td></tr><tr><td>13-05-2024 10:25:28</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	13-05-2024 10:57:20	Atique Salmani	Completed	Tv allready working 13 flor 1307 client required remooved cameras need to reinstalled as soon as possible		13-05-2024 10:25:28	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
13-05-2024 10:57:20	Atique Salmani	Completed	Tv allready working 13 flor 1307 client required remooved cameras need to reinstalled as soon as possible																	
13-05-2024 10:25:28	Atique Salmani	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>22-04-2024 03:08:25</td><td>Atique Salmani</td><td>6 floor passage camera issue resolved Lobby ground floor issue resolved Main gate done but cable joint and also very tite soniya on/off 8 floorstair camera collect 3 floor passage camera collect 14 floor camera collect Back side carpark can't chek camera .</td></tr><tr><td>10-04-2024 03:12:34</td><td>Atique Salmani</td><td>Main gate camera new cabling 70/80 mtr and other options near camera used adaptor And both trueview nvr 2 sata slot model nmbr given in group and 9 th floor SMPS need to changed .</td></tr></tbody></table>					Date Time	Technician Name	Remark	22-04-2024 03:08:25	Atique Salmani	6 floor passage camera issue resolved Lobby ground floor issue resolved Main gate done but cable joint and also very tite soniya on/off 8 floorstair camera collect 3 floor passage camera collect 14 floor camera collect Back side carpark can't chek camera .	10-04-2024 03:12:34	Atique Salmani	Main gate camera new cabling 70/80 mtr and other options near camera used adaptor And both trueview nvr 2 sata slot model nmbr given in group and 9 th floor SMPS need to changed .						
Date Time	Technician Name	Remark																		
22-04-2024 03:08:25	Atique Salmani	6 floor passage camera issue resolved Lobby ground floor issue resolved Main gate done but cable joint and also very tite soniya on/off 8 floorstair camera collect 3 floor passage camera collect 14 floor camera collect Back side carpark can't chek camera .																		
10-04-2024 03:12:34	Atique Salmani	Main gate camera new cabling 70/80 mtr and other options near camera used adaptor And both trueview nvr 2 sata slot model nmbr given in group and 9 th floor SMPS need to changed .																		