## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

Service Status Details : VE7291								
Priority:	Low							
Created By:	Admin - Apurva Vajaria							
Complaint Mob. No. :	8169358756							
Technician Name :	Siddhesh Chavan		Technician Mobile	8080922985				
Ticket Type :	Complain	Date & Time :	06-01-2023 11:19:49	-01-2023 11:19:49				
Vendor Details :			_					
Company Name/Client Name :	Rahul International - Mira Road	Customer's Mobile :	8169358756	Name :	Nisha Madam			
Address:								
Mumbai , , , , M	aharashtra							
AMC Details:								
Expiry Date :	01-01-1970 05:30:00		Type:					
Product Name:	CCTV							
Complain :	Some cameras blur, Some cameras video issue, Renaming of all cameras Cross mark at 3rd, 4th floor and 5th floor							
Technician Comment :	ground floor to 3rd floor all camera nameing done and also camera blur issue resolved and no video issue resolved 4th floor already nameing done ground floor reception side to camera new video because camera not connect for ground floor dvr 1st floor 112 room no cable no camera 3rd floor 305 306 307 room no cable no camera and all camera working ok							
Complain Operator :	Desktop - Apurva Vajaria							
Remark :	ground floor to 3rd floor all camera nameing done and also camera blur issue resolved and no video issue resolved 4th floor already nameing done ground floor reception side to camera new video because camera not connect for ground floor dvr 1st floor 112 room no cable no camera 3rd floor 305 306 307 room no cable no camera and all camera working ok							

<b>Status History</b>	Date Time	Technician Name	Status	Remark	Sign	
:	07-01-2023 05:33:42	Siddhesh Chavan	Completed	ground floor to 3rd floor all camera nameing done and also camera blur issue resolved and no video issue resolved 4th floor already nameing done ground floor reception side to camera new video because camera not connect for ground floor dvr 1st floor 112 room no cable no camera 3rd floor 305 306 307 room no cable no camera and all camera working ok		
	07-01-2023 05:28:26	Siddhesh Chavan	New		-	
	07-01-2023 10:48:13	Siddhesh Chavan	New		-	
	06-01-2023 11:19:56	Siddhesh Chavan	New		-	
Previous Complain	Date Time	Technician Name	Remark			
History:	27-12-2022 01:03:18	Siddhesh Chavan				
	10-12-2022 11:36:19	Siddhesh Chavan	1) cm sir cabine cctv view issue resolved 2) dvr side hdmi extender cat 6 cable disconnect re contact cable and issue resolved 3) Darshan sir pc software download and all dvr and NVR viewing done 4) 8 th floor NVR power disconnect and reconnect supply and all camera working ok 5)principal sir pc software install pending 6)fees counter inside camera working ok 7) Darshan sir and Davies sir software training pending			