

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE9747																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	7609090505																													
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																										
Ticket Type :	New Installation	Date & Time :	06-10-2023 12:59:48																											
Vendor Details :																														
Company Name/Client Name :	Arihant Enclave(Chheda Group Andheri Site)	Customer's Mobile :	7609090505	Name :	Pankhil Sir																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
Product Name :	VDP																													
Complain :	flat no. 901 VDP need to install																													
Technician Comment :	Cable inside the box camera installation boath side crimping and temprrory screen on chekby client screen ha d over to client																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	Cable inside the box camera installation boath side crimping and temprrory screen on chekby client screen ha d over to client																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>12-12-2023 02:50:29</td><td>Atique Salmani</td><td>Completed</td><td></td><td>-</td></tr><tr><td>09-10-2023 02:17:02</td><td>Atique Salmani</td><td>Client Side</td><td>Cable inside the box camera installation boath side crimping and temprrory screen on chekby client screen ha d over to client</td><td></td></tr><tr><td>09-10-2023 12:49:00</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>06-10-2023 04:27:59</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	12-12-2023 02:50:29	Atique Salmani	Completed		-	09-10-2023 02:17:02	Atique Salmani	Client Side	Cable inside the box camera installation boath side crimping and temprrory screen on chekby client screen ha d over to client		09-10-2023 12:49:00	Atique Salmani	New		-	06-10-2023 04:27:59	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																										
12-12-2023 02:50:29	Atique Salmani	Completed		-																										
09-10-2023 02:17:02	Atique Salmani	Client Side	Cable inside the box camera installation boath side crimping and temprrory screen on chekby client screen ha d over to client																											
09-10-2023 12:49:00	Atique Salmani	New		-																										
06-10-2023 04:27:59	Atique Salmani	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>11-12-2023 02:36:20</td><td>Siddhesh Chavan</td><td>client side issue vdp install pending</td></tr><tr><td>01-12-2023 10:58:19</td><td>Siddhesh Chavan</td><td>1702 and 1004 vdp install and training done</td></tr></tbody></table>					Date Time	Technician Name	Remark	11-12-2023 02:36:20	Siddhesh Chavan	client side issue vdp install pending	01-12-2023 10:58:19	Siddhesh Chavan	1702 and 1004 vdp install and training done																
Date Time	Technician Name	Remark																												
11-12-2023 02:36:20	Siddhesh Chavan	client side issue vdp install pending																												
01-12-2023 10:58:19	Siddhesh Chavan	1702 and 1004 vdp install and training done																												