Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE8920 Low **Priority** : **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9867000996 **No. : Technician Name** Atique Salmani **Technician Mobile** 8080922984 Complain 20-07-2023 11:20:06 **Ticket Type : Date & Time :** Vendor Details : Trivikram TVS Customer's Mobile 9867000996 Prakash Sir Company Name : Name/Client Name Service Center Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** CCTV **Complain**: Some camera issue collect visiting charges 750/-Camera nmbr 4 cable need to lay 60/70 MTR cable 4+1 required and all cameras bneed to set Technician **Comment**: angel and also lense cleaning. Complain Desktop - Apurva Vajaria **Operator** : **Remark** : Camera nmbr 4 cable need to lay 60/70 MTR cable 4+1 required and all cameras bneed to set angel and also lense cleaning. **Status History :** Date Time **Technician Name** Status Remark Sign 18-08-2023 04:12:08 Atique Salmani Closed 20-07-2023 01:29:20 Atique Salmani Work Camera nmbr 4 cable Pending need to lay 60/70 MTR cable 4+1 required and all cameras bneed to set angel and also lense cleaning. 20-07-2023 11:21:53 Atique Salmani New Previous Technician **Date Time** Remark **Complain History** Name • 23-11-2021 Munna Gupta We visit in Trivikram tvs Service center for. Need to 03 bullet camera BNC connector problem and 1 ip camera network ip 03:13:38 unreachable. Frame rate and bitrate setting. ip camera ip address setting and password reset. additional new items used bnc connector 06 nos, Rj45 connector 02. Work completed. Cctv system working properly.