## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

<b>Service Status Det</b>	tails: VE1051						
Priority:	High						
Created By:	Admin - Apurva Vajaria						
Complaint Mob.	9987588911						
Technician Name :	Ravi Rajbhar		Technician Mobile :		8080922965		
Ticket Type :	Complain	Date & Time :	03-02-2020 12:09:14				
Vendor Details :							
Company Name/Client Name :	Chandrakant Residency	Customer's Mobile :	9987588911		Name :	Prashant Sir	
Address:							
Thane , Maxus Mall Road, Padmavati Nagar, Bhayandar West, Mira Bhayandar, Maharashtra, India , , , , Maharashtra							
AMC Details:							
Expiry Date :	31-01-2021 12:00:00		Type:		Non-Comprehensive		
<b>Product Name:</b>	Intercom						
Complain:	B 602 ph is not working						
Technician Comment :	b wing 603 intercom issue resolved and ok working done only juction to flat wearing other port in punching also						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	b wing $603$ intercom issue resolved and ok working done only juction to flat wearing other port in punching also						
<b>Status History:</b>	Date Time	Technician Name	Status	Remark			Sign
	15-09-2020 05:07:17	Ravi Rajbhar	Closed	-		-	
	03-02-2020 01:07:44	Ravi Rajbhar	Completed	b wing 603 intercom issue resolved and ok working done only juction to flat wearing other port in punching also		Shiva	
	03-02-2020 01:02:11	Ravi Rajbhar	New				-
	03-02-2020 01:02:05	Ravi Rajbhar	New				-
	03-02-2020 12:09:15	Ravi Rajbhar	New				-
Previous Complain History :	Date Time	Technician Name	Remark				
	07-09-2020 01:09:09	Atique Salmani	cctv issue main gate camera not working reset camera and working ok. and intetcom 3 line issue repunch from crone flate nmbr B Wing 602 bwing 103 and 403 cable trace and line ok instrument keypad issue need to changed.				
	12-08-2020 11:36:20 AnilYadav Anil Visited an changed ballon and now working ok						