Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status De	tails: VE1576							
Priority:	Low							
Created By:	Admin - Apurva Vajaria							
Complaint Mob. No. :	9987588911							
Technician Name :	Anil Yadav		Technician Mobile :	8080922983				
Ticket Type :	Complain	Date & Time :	20-07-2020	0 01:20:26				
Vendor Details :	_		•					
Company Name/Client Name:	Chandrakant Residency	Customer's Mobile :	998758891	1	Name: Prashant Sir		shant Sir	
Address:								
Thane , Maxus Mall Road, Padmavati Nagar, Bhayandar West, Mira Bhayandar, Maharashtra, India , , , Maharashtra								
AMC Details:								
Expiry Date :	31-01-2021 12:00:00		Type:	Type:		Non-Comprehensive		
Product Name:	Intercom							
Complain:	1 phone issue security cabin							
Technician Comment :	Card no.4 all 16 line incoming not ringing because mother board to card cable was dead. l do install new cable now all 16 line working.							
Complain Operator :	Desktop - Apurva Vajaria							
Remark:	Card no.4 all 16 line incoming not ringing because mother board to card cable was dead. l do install new cable now all 16 line working.							
Status History :	Date Time	Technician Name	Status		Remark		Sign	
	23-07-2020 04:06:40	AnilYadav	Completed	not ring board to	.4 all 16 line incoming because mother of card cable was detail new cable now aworking.	r ad.		
	22-07-2020 05:09:54	AnilYadav	New				-	
	20-07-2020 06:21:32	AnilYadav	Work Pending	card rin recheck 602 b60 a602 11	tercom line ok but ger issue need to card 7 line issue b 3 b601 b 304a 303 11 office. cctv chec nmbr 2 issue resolv	k	Dealy	
	20-07-2020 01:20:33	AnilYadav	New				-	
	20-07-2020 01:20:26	AnilYadav	New				-	

Previous Complain History :	Date Time	Technician Name	Remark		
	07-09-2020 01:09:09	Atique Salmani	cctv issue main gate camera not working reset camera and working ok. and intetcom 3 line issue repunch from crone flate nmbr B Wing 602 bwing 103 and 403 cable trace and line ok instrument keypad issue need to changed.		
	12-08-2020 11:36:20	AnilYadav	Anil Visited an changed ballon and now working ok		