




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE947</b>																														
<b>Priority :</b>	High																													
<b>Created By :</b>	Admin - Apurva Vajaria																													
<b>Complaint Mob. No. :</b>	9987588911																													
<b>Technician Name :</b>	Ravi Rajbhar		<b>Technician Mobile :</b>	8080922965																										
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	20-01-2020 06:24:32																											
<b>Vendor Details :</b>																														
<b>Company Name/Client Name :</b>	Chandrakant Residency	<b>Customer's Mobile :</b>	9987588911	<b>Name :</b>	Prashant Sir																									
<b>Address :</b>																														
Thane , Maxus Mall Road, Padmavati Nagar, Bhayandar West, Mira Bhayandar, Maharashtra, India , , , Maharashtra																														
<b>AMC Details :</b>																														
<b>Expiry Date :</b>	31-01-2021 12:00:00		<b>Type :</b>	Non-Comprehensive																										
<b>Product Name :</b>	Intercom																													
<b>Complain :</b>	A/ 701																													
<b>Technician Comment :</b>	a wing 701 intencom issue resolved and ok working done																													
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																													
<b>Remark :</b>	a wing 701 intencom issue resolved and ok working done																													
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>15-09-2020 05:07:15</td><td>Ravi Rajbhar</td><td>Closed</td><td></td><td>-</td></tr><tr><td>21-01-2020 11:31:31</td><td>Ravi Rajbhar</td><td>Completed</td><td>a wing 701 intencom issue resolved and ok working done</td><td></td></tr><tr><td>20-01-2020 06:24:42</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>20-01-2020 06:24:33</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	15-09-2020 05:07:15	Ravi Rajbhar	Closed		-	21-01-2020 11:31:31	Ravi Rajbhar	Completed	a wing 701 intencom issue resolved and ok working done		20-01-2020 06:24:42	Ravi Rajbhar	New		-	20-01-2020 06:24:33	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																										
15-09-2020 05:07:15	Ravi Rajbhar	Closed		-																										
21-01-2020 11:31:31	Ravi Rajbhar	Completed	a wing 701 intencom issue resolved and ok working done																											
20-01-2020 06:24:42	Ravi Rajbhar	New		-																										
20-01-2020 06:24:33	Ravi Rajbhar	New		-																										
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>07-09-2020 01:09:09</td><td>Atique Salmani</td><td>cctv issue main gate camera not working reset camera and working ok. and intetcom 3 line issue repunch from crone flate nmbr B Wing 602 bwing 103 and 403 cable trace and line ok instrument keypad issue need to changed.</td></tr><tr><td>12-08-2020 11:36:20</td><td>AnilYadav</td><td>Anil Visited an changed ballon and now working ok</td></tr></tbody></table>					Date Time	Technician Name	Remark	07-09-2020 01:09:09	Atique Salmani	cctv issue main gate camera not working reset camera and working ok. and intetcom 3 line issue repunch from crone flate nmbr B Wing 602 bwing 103 and 403 cable trace and line ok instrument keypad issue need to changed.	12-08-2020 11:36:20	AnilYadav	Anil Visited an changed ballon and now working ok																
Date Time	Technician Name	Remark																												
07-09-2020 01:09:09	Atique Salmani	cctv issue main gate camera not working reset camera and working ok. and intetcom 3 line issue repunch from crone flate nmbr B Wing 602 bwing 103 and 403 cable trace and line ok instrument keypad issue need to changed.																												
12-08-2020 11:36:20	AnilYadav	Anil Visited an changed ballon and now working ok																												