Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Details : VE15450									
Priority:	Low								
Created By:	Admin - Apurva Vajaria								
Complaint Mob. No. :	9320524244								
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965					
Ticket Type:	Complain	Date & Time :	01-08-2025 10:03:30						
Vendor Details :									
Company Name/Client Name :	Barcelona Miraroad	Customer's Mobile :	9320524244	Name:	Prem Shukla				
Address:									
Mumbai , , , , Maharashtra									
AMC Details :									
Expiry Date :	01-01-1970 05:30:00		Type:						
Product Name:	Access								
Complain:	1)Lift display is not working at B2 2)Access device B wing is not working 3)B wing door not getting close								
Technician Comment :	Lift video door phone issue resolved and ok working done B2 meters room poe switch to nvr rack cable faulty need to change and poe switch issue								
Complain Operator :	Desktop - Apurva Vajaria								
Remark:	Lift video door phone issue resolved and ok working done B2 meters room poe switch to nvr rack cable faulty need to change and poe switch issue								

Status History :	Date Time	Technician Name	Statu	18	Remark	Sign
	05-08-2025 05:07:14	Ravi Rajbhar	Complete	ed	Lift video door phone issue resolved and ok working done B2 meters room poe switch to nvr rack cable faulty need to change and poe switch issue	Ø
	05-08-2025 05:07:14	Ravi Rajbhar	Complete	ed	Lift video door phone issue resolved and ok working done B2 meters room poe switch to nvr rack cable faulty need to change and poe switch issue	B
	05-08-2025 10:54:37	Ravi Rajbhar	New			-
	01-08-2025 11:07:41	Ravi Rajbhar	Work Pending		B wing door access issue resolved changed new SMPS 12 volt 5 amps inside near door above forceling and chek all 3 door access with Vivek Sharma supervisor and electrician working ok lift door bell camera painding.	मिलिल
	01-08-2025 11:07:41	Ravi Rajbhar	Work Pending		B wing door access issue resolved changed new SMPS 12 volt 5 amps inside near door above forceling and chek all 3 door access with Vivek Sharma supervisor and electrician working ok lift door bell camera painding.	मित्रितात
	01-08-2025 10:03:39	Ravi Rajbhar	New			-
Previous Complain	Date Time				Technician Name	Remark
History:	26-08-2025 03:21:49			Ravi Rajbhar		
	26-08-2025 03:21:01			Ravi Rajbhar		