Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 Support : | **W** : www.vallabhenterprises.com **E** : vallabhsecure@yahoo.co.in

Service Status Details : VE1198 High **Priority** : **Created By :** Admin - Apurva Vajaria Complaint 9619151939 Mob. No. : Technician Zainul Shaikh **Technician Mobile** 8080922971 Name : Complain Date & Time : 21-02-2020 11:36:47 **Ticket Type :** Vendor Details : Taj Hotel Customer's Mobile 9619151939 Name : **Purnanand Petwal** Company Name/Client Santacruz Name : Address : Mumbai, Santacruz East, Mumbai, Maharashtra, India, , 400099, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** intrusion **Complain**: need to show how messages are coming in phone all need to check rooms for Serving in 4th and 5th flr panel sim card change and gsm configuration done. 3 new nos added and 1 **Technician** removed. in new sim sms configuration Activation pending from distributor side. in 344 room **Comment** : both bus module change now loss issue solved. in 539 room tmp issue solved but still under observation. 351 and 642 glass door lock from client side Complain Desktop - Apurva Vajaria **Operator** : **Remark** : in 4th and 5th flr panel sim card change and gsm configuration done. 3 new nos added and 1 removed. in new sim sms configuration Activation pending from distributor side. in 344 room both bus module change now loss issue solved. in 539 room tmp issue solved but still under observation. 351 and 642 glass door lock from client side **Status History :** Date Time **Technician Name** Status Remark Sign 21-02-2020 ZainulShaikh Completed in 4th and 5th flr panel sim card Lor ~ change and gsm configuration done. 07:12:11 3 new nos added and 1 removed. in new sim sms configuration Activation pending from distributor side. in 344 room both bus module change now loss issue solved. in 539 room tmp issue solved but still under observation. 351 and 642 glass door lock from client side 21-02-2020 ZainulShaikh New 02:10:23 21-02-2020 ZainulShaikh New 11:36:47

Previous Complain History :	Date Time	Technician Name	Remark
	13-06-2023 11:07:42	Ravi Rajbhar	437 need to change small cricit with magnetic contact 446 issue resloved 445 issue resloved
	22-08-2022 01:13:19	Prashant Nikalje	