



Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE3966					
Priority :	Low				
Created By :	Admin - Apurva Vajaria				
Complaint Mob. No. :	9022904145				
Technician Name :	Neeraj Chauhan		Technician Mobile :	8898885764	
Ticket Type :	Complain	Date & Time :	04-10-2021 03:42:57		
Vendor Details :					
Company Name/Client Name :	VIP PLAZA CO OPERATIVE PREMISES SOCIETY LTD	Customer's Mobile :	9022904145	Name :	Raghu Sir
Address :					
Mumbai , , , , Maharashtra					
AMC Details :					
Expiry Date :	12-01-2021 12:00:00		Type :	Comprehensive	
Product Name :	CCTV				
Complain :	3-4 camera issue & some camera settings to be done				
Technician Comment :	pm work completed. all camera are working. only two camera having problem one taken to office one camera near Awing Libby between to lift need to be checked pm work completed recording on for all cameras.				
Complain Operator :	Desktop - Apurva Vajaria				
Remark :	pm work completed. all camera are working. only two camera having problem one taken to office one camera near Awing Libby between to lift need to be checked pm work completed recording on for all cameras.				
Status History :	Date Time	Technician Name	Status	Remark	Sign
	05-10-2021 09:21:41	Neeraj Chauhan	Completed	pm work completed. all camera are working. only two camera having problem one taken to office one camera near Awing Libby between to lift need to be checked pm work completed recording on for all cameras.	
	05-10-2021 04:13:03	Neeraj Chauhan	New		-
	04-10-2021 07:53:31	Neeraj Chauhan	Work Pending	3 dvr ground issues not 2 camera works pending.	
	04-10-2021 03:43:09	Neeraj Chauhan	New		-
	04-10-2021 03:42:57	Neeraj Chauhan	New		-

Previous Complain History :	Date Time	Technician Name	Remark
	15-02-2022 11:37:04	Ravi Rajbhar	
	11-02-2022 02:54:37	Atique Salmani	terrace camera issue resolved by reconnection and working ok b302 b 204 2 camera need to changed one is pinkish and is more disturbance .