




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE4750</b>																														
<b>Priority :</b>	Low																													
<b>Created By :</b>	Admin - Apurva Vajaria																													
<b>Complaint Mob. No. :</b>	9022904145																													
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																										
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	11-02-2022 02:54:37																											
<b>Vendor Details :</b>																														
Company Name/Client Name :	VIP PLAZA CO OPERATIVE PREMISES SOCIETY LTD	Customer's Mobile :	9022904145	Name :	Raghu Sir																									
<b>Address :</b>																														
Mumbai , , , , Maharashtra																														
<b>AMC Details :</b>																														
<b>Expiry Date :</b>	12-01-2021 12:00:00		<b>Type :</b>	Comprehensive																										
<b>Product Name :</b>	CCTV																													
<b>Complain :</b>	3 cameras off issue																													
<b>Technician Comment :</b>	terrace camera issue resolved by reconnection and working ok b302 b 204 2 camera need to changed one is pinkish and is more disturbance .																													
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																													
<b>Remark :</b>	terrace camera issue resolved by reconnection and working ok b302 b 204 2 camera need to changed one is pinkish and is more disturbance .																													
<b>Status History :</b>	<table border="1"> <thead> <tr> <th>Date Time</th> <th>Technician Name</th> <th>Status</th> <th>Remark</th> <th>Sign</th> </tr> </thead> <tbody> <tr> <td>12-02-2022 02:23:02</td> <td>Atique Salmani</td> <td>Completed</td> <td>terrace camera issue resolved by reconnection and working ok b302 b 204 2 camera need to changed one is pinkish and is more disturbance .</td> <td></td> </tr> <tr> <td>12-02-2022 10:23:15</td> <td>Atique Salmani</td> <td>New</td> <td></td> <td>-</td> </tr> <tr> <td>11-02-2022 02:54:54</td> <td>Atique Salmani</td> <td>New</td> <td></td> <td>-</td> </tr> <tr> <td>11-02-2022 02:54:38</td> <td>Atique Salmani</td> <td>New</td> <td></td> <td>-</td> </tr> </tbody> </table>					Date Time	Technician Name	Status	Remark	Sign	12-02-2022 02:23:02	Atique Salmani	Completed	terrace camera issue resolved by reconnection and working ok b302 b 204 2 camera need to changed one is pinkish and is more disturbance .		12-02-2022 10:23:15	Atique Salmani	New		-	11-02-2022 02:54:54	Atique Salmani	New		-	11-02-2022 02:54:38	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																										
12-02-2022 02:23:02	Atique Salmani	Completed	terrace camera issue resolved by reconnection and working ok b302 b 204 2 camera need to changed one is pinkish and is more disturbance .																											
12-02-2022 10:23:15	Atique Salmani	New		-																										
11-02-2022 02:54:54	Atique Salmani	New		-																										
11-02-2022 02:54:38	Atique Salmani	New		-																										
<b>Previous Complain History :</b>	<table border="1"> <thead> <tr> <th>Date Time</th> <th>Technician Name</th> <th>Remark</th> </tr> </thead> <tbody> <tr> <td>11-02-2022 02:54:28</td> <td>Atique Salmani</td> <td>ppm done dvr nmbr 2. 4 cameras connected only was being hang so formatted hdd and after permetion raghuji so recording on from today . and keep on under observation.</td> </tr> <tr> <td>28-01-2022 11:29:06</td> <td>Ravi Rajbhar</td> <td>B wing duct side cable check but office side cable &amp; phone not found b wing busment cron weak ( crystal 48 line old version system password missing)</td> </tr> </tbody> </table>					Date Time	Technician Name	Remark	11-02-2022 02:54:28	Atique Salmani	ppm done dvr nmbr 2. 4 cameras connected only was being hang so formatted hdd and after permetion raghuji so recording on from today . and keep on under observation.	28-01-2022 11:29:06	Ravi Rajbhar	B wing duct side cable check but office side cable & phone not found b wing busment cron weak ( crystal 48 line old version system password missing)																
Date Time	Technician Name	Remark																												
11-02-2022 02:54:28	Atique Salmani	ppm done dvr nmbr 2. 4 cameras connected only was being hang so formatted hdd and after permetion raghuji so recording on from today . and keep on under observation.																												
28-01-2022 11:29:06	Ravi Rajbhar	B wing duct side cable check but office side cable & phone not found b wing busment cron weak ( crystal 48 line old version system password missing)																												