




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE4854																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	7045685875																								
Technician Name :	Neeraj Chauhan		Technician Mobile :	8898885764																					
Ticket Type :	Complain	Date & Time :	23-02-2022 10:39:23																						
Vendor Details :																									
Company Name/Client Name :	Jyoti Fire Panvel Site	Customer's Mobile :	7045685875	Name :	Rahul Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	Fire																								
Complain :	fire testing																								
Technician Comment :	same detector is fualty need to replace and cable short need to check cabling. work is not complete, work pending																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	same detector is fualty need to replace and cable short need to check cabling. work is not complete, work pending																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>23-02-2022 06:46:41</td><td>Neeraj Chauhan</td><td>Work Pending</td><td>same detector is fualty need to replace and cable short need to check cabling. work is not complete, work pending</td><td></td></tr><tr><td>23-02-2022 10:39:42</td><td>Neeraj Chauhan</td><td>New</td><td></td><td>-</td></tr><tr><td>23-02-2022 10:39:23</td><td>Neeraj Chauhan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	23-02-2022 06:46:41	Neeraj Chauhan	Work Pending	same detector is fualty need to replace and cable short need to check cabling. work is not complete, work pending		23-02-2022 10:39:42	Neeraj Chauhan	New		-	23-02-2022 10:39:23	Neeraj Chauhan	New		-
Date Time	Technician Name	Status	Remark	Sign																					
23-02-2022 06:46:41	Neeraj Chauhan	Work Pending	same detector is fualty need to replace and cable short need to check cabling. work is not complete, work pending																						
23-02-2022 10:39:42	Neeraj Chauhan	New		-																					
23-02-2022 10:39:23	Neeraj Chauhan	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead></table>					Date Time	Technician Name	Remark																	
Date Time	Technician Name	Remark																							