Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Deta	ails · VF15401				E. vanabusecure@yanoo.co.m						
	######################################										
Priority:	Low										
Created By:	Admin - Apurva Vajaria										
Complaint Mob. No. :	9833008982										
Technician Name :	Siddhesh Chavan		Technicia	ian Mobile : 8080922985							
Ticket Type :	Complain	Date & Time :	28-07-2025 03:06:45								
Vendor Details:											
Company Name/Client Name :	Brijkutir Bldg	Customer's Mobile :	98330089	982	Name :	Rajan Bhai					
Address :											
Mumbai , , , , Maha	arashtra										
AMC Details :											
Expiry Date :	01-01-1970 05:30:00		Type:								
Product Name:	Intercom										
	1)Flt no 21 Phone change rcent bt nt wrking 2)Flt no 41 last visit flat lock Intercom issue 3)Flat no. 111 cheked the cable and removed rojet box totally rushted and also reconnetion from duct side 4)Flat no. 34 cable issue need to check										
Technician Comment :	21 intercom line issue resolved 41 intercom line issue resolved phone issue 84 phone issue need to send phone 111 working ok 34 cable issue flat to floor junction										
Complain Operator :	Desktop - Apurva Vajaria										
Remark:	21 intercom line issue resolved 41 intercom line issue resolved phone issue 84 phone issue need to send phone 111 working ok 34 cable issue flat to floor junction										
Status History :	Date Time	Technician Name	Status	R	emark	Sign					
	28-07-2025 06:14:17	Siddhesh Chavan	Completed	41 intercom li phone issue 8 need to send	4 cable issue flat	Son					
	28-07-2025 03:06:56	Siddhesh Chavan	New			-					
Previous	Date Time	Technician Name	Remark								
Complain History :	30-07-2025 11:11:32	MaroofRaza	flat no. 84 New phone installed and charges collected								
	24-07-2025 03:51:56	Rahul Mhapralkar	141 flat intercom issue resolved, 41 flat no flat lock, 34 no cable not connected to device cable not found, back gate intercom issue resolved.								