## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

E: valiabilisecure@yalioo.co.iii							
Service Status De	etails: VE12976						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No.:	8169144587						
Technician Name :	Rahul Mhapralkar		Technician Mobile		9168762949		
Ticket Type :	AMC visiting	Date & Time :	14-10-2024 01:02:58				
Vendor Details :							
Company Name/Client Name :	Corporate Square Ghatkopar	Customer's Mobile :	8169144587		Name :	Rajendra Sir	
Address:							
Mumbai , , , 4000	076 , Maharashtra						
AMC Details :	-		_		_		
Expiry Date :	01-01-1970 05:30:0	00	Type:				
<b>Product Name:</b>	Ppm						
Complain:	CCTV/Access PPM need to do						
Technician Comment :	CCTV & ACCESS PPM DONE 1 NO DVR RECORDING ISSUE RESOLVED, 10TH FLOOR CAMERA FAULTY. 3RD FLOOR CAMERA BNC CONNECTOR CHANGE.						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	CCTV & ACCESS PPM DONE 1 NO DVR RECORDING ISSUE RESOLVED, 10TH FLOOR CAMERA FAULTY. 3RD FLOOR CAMERA BNC CONNECTOR CHANGE.						
<b>Status History</b> :	Date Time	Technician Name	Status		Remark		Sign
	14-10-2024 03:12:29	Rahul Mhapralkar	Completed	CCTV & ACCESS PPM DONE 1 NO DVR RECORDING ISSUE RESOLVED, 10TH FLOOR CAMERA FAULTY. 3RD FLOOR CAMERA BNC CONNECTOR CHANGE.		EKX/pg	
	14-10-2024 01:03:21	Rahul Mhapralkar	New			-	
Previous	Date Time	Technician Name	Remark				
Complain History :	17-08-2023 05:58:31	YogeshDesai	Old DVR of 16 channel repaired and installed at A wing of cooperate square DVR working ok . Stand by DVR taken back to office . Also DVR no 3 is online can be viewed on ivms software. Work completed				
	27-07-2023 03:28:07	Kalpesh SubhashGurav  DVR No.3 10th floor camera Faulty DVR no3 16 number port issue Lift camera issue Pending Required Lift technician DVR to lobby TV 100 meter CAT 6 cable Required Lobby access (identx) not working properly HDMI splitter 3 in1out Required. hdmi to rj 45 converter Required					an DVR