




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE2134																														
Priority :	High																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	8169144587																													
Technician Name :	Shiva Meena		Technician Mobile :	7489567735																										
Ticket Type :	Complain	Date & Time :	29-10-2020 12:54:53																											
Vendor Details :																														
Company Name/Client Name :	Corporate Square Ghatkopar	Customer's Mobile :	8169144587	Name :	Rajendra Sir																									
Address :																														
Mumbai , , , 400076 , Maharashtra																														
AMC Details :																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
Product Name :	CCTV																													
Complain :	2 -3 camers issue																													
Technician Comment :	how camera working mote HDMI extender issue																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	how camera working mote HDMI extender issue																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>02-11-2020 10:55:10</td><td>Shiva Meena</td><td>New</td><td></td><td>-</td></tr><tr><td>29-10-2020 07:08:05</td><td>Shiva Meena</td><td>Work Pending</td><td>how camera working mote HDMI extender issue</td><td></td></tr><tr><td>29-10-2020 12:55:16</td><td>Shiva Meena</td><td>New</td><td></td><td>-</td></tr><tr><td>29-10-2020 12:54:53</td><td>Shiva Meena</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	02-11-2020 10:55:10	Shiva Meena	New		-	29-10-2020 07:08:05	Shiva Meena	Work Pending	how camera working mote HDMI extender issue		29-10-2020 12:55:16	Shiva Meena	New		-	29-10-2020 12:54:53	Shiva Meena	New		-
Date Time	Technician Name	Status	Remark	Sign																										
02-11-2020 10:55:10	Shiva Meena	New		-																										
29-10-2020 07:08:05	Shiva Meena	Work Pending	how camera working mote HDMI extender issue																											
29-10-2020 12:55:16	Shiva Meena	New		-																										
29-10-2020 12:54:53	Shiva Meena	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>27-07-2023 03:28:07</td><td>Kalpesh SubhashGurav</td><td>DVR No.3 10th floor camera Faulty DVR no3 16 number port issue Lift camera issue Pending Required Lift technician DVR to lobby TV 100 meter CAT 6 cable Required Lobby access (identx) not working properly HDMI splitter 3 in1out Required. hdmi to rj 45 converter Required</td></tr><tr><td>16-05-2023 09:57:14</td><td>Atique Salmani</td><td>Ther is wire cut by mouse so rejoin 8 core wire and also covered by 25 mm flexible pipe and also reset date n time and add 1 security person finger .all completed.</td></tr></tbody></table>					Date Time	Technician Name	Remark	27-07-2023 03:28:07	Kalpesh SubhashGurav	DVR No.3 10th floor camera Faulty DVR no3 16 number port issue Lift camera issue Pending Required Lift technician DVR to lobby TV 100 meter CAT 6 cable Required Lobby access (identx) not working properly HDMI splitter 3 in1out Required. hdmi to rj 45 converter Required	16-05-2023 09:57:14	Atique Salmani	Ther is wire cut by mouse so rejoin 8 core wire and also covered by 25 mm flexible pipe and also reset date n time and add 1 security person finger .all completed.																
Date Time	Technician Name	Remark																												
27-07-2023 03:28:07	Kalpesh SubhashGurav	DVR No.3 10th floor camera Faulty DVR no3 16 number port issue Lift camera issue Pending Required Lift technician DVR to lobby TV 100 meter CAT 6 cable Required Lobby access (identx) not working properly HDMI splitter 3 in1out Required. hdmi to rj 45 converter Required																												
16-05-2023 09:57:14	Atique Salmani	Ther is wire cut by mouse so rejoin 8 core wire and also covered by 25 mm flexible pipe and also reset date n time and add 1 security person finger .all completed.																												