Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE2546 Low **Priority** : **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 8169144587 **No.** : Technician Ravi Rajbhar **Technician Mobile** 8080922965 Name : New Installation 07-01-2021 01:31:48 **Ticket Type :** Date & Time : **Vendor Details : Corporate Square** Customer's Mobile 8169144587 Rajendra Sir Company Name : Name/Client Ghatkopar Name : Address : Mumbai,,,400076, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** Access add 100 cards **Complain**: f100 ground floor (password reset and finger with 25 card add and 5 card admin add in divice Technician P1 - same card add with lift side divice password reset P2 same card add only divice **Comment**: Complain Desktop - Apurva Vajaria **Operator** : **Remark** : f100 ground floor (password reset and finger with 25 card add and 5 card admin add in divice P1 - same card add with lift side divice password reset P2 same card add only divice **Status History :** Date Time **Technician Name** Status Remark Sign 15-01-2021 01:45:23 Ravi Rajbhar Completed f100 ground floor (password reset and finger with 25 card add and 5 card admin add in GS_ M divice P1 - same card add with lift side divice password reset P2 same card add only divice 14-01-2021 07:35:36 Ravi Rajbhar New 13-01-2021 10:57:58 Ravi Rajbhar New _ 13-01-2021 10:01:56 Ravi Rajbhar New _ 07-01-2021 04:23:08 Ravi Rajbhar Work Pending 07-01-2021 01:32:02 Ravi Rajbhar New 07-01-2021 01:31:48 Ravi Rajbhar New _

Previous Complain History :	Date Time	Technician Name	Remark
	27-07-2023 03:28:07	Kalpesh SubhashGurav	DVR No.3 10th floor camera Faulty DVR no3 16 number port issue Lift camera issue Pending Required Lift technician DVR to lobby TV 100 meter CAT 6 cable Required Lobby access (identx) not working properly HDMI splitter 3 in1out Required. hdmi to rj 45 converter Required
	16-05-2023 09:57:14	Atique Salmani	Ther is wire cut by mouse so rejoint 8 core wire and also coverd by 25 mm flexible pipe and also reset date n time and add 1 security person finger .all completed.