

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE2667																																								
Priority :	Low																																							
Created By :	Admin - Apurva Vajaria																																							
Complaint Mob. No. :	8169144587																																							
Technician Name :	Yogesh Desai		Technician Mobile :	8080922963																																				
Ticket Type :	New Installation	Date & Time :	05-02-2021 12:44:33																																					
Vendor Details :																																								
Company Name/Client Name :	Corporate Square Ghatkopar	Customer's Mobile :	8169144587	Name :	Rajendra Sir																																			
Address :																																								
Mumbai , , , 400076 , Maharashtra																																								
AMC Details :																																								
Expiry Date :	01-01-1970 05:30:00		Type :																																					
Product Name :	CCTV																																							
Complain :	installation of camera																																							
Technician Comment :	4 camera installation done 2 old reinstall and 2 new camera dvr side cabling not complete																																							
Complain Operator :	Desktop - Apurva Vajaria																																							
Remark :	4 camera installation done 2 old reinstall and 2 new camera dvr side cabling not complete																																							
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>05-03-2021 09:54:45</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr><tr><td>09-02-2021 06:46:39</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr><tr><td>06-02-2021 03:55:37</td><td>YogeshDesai</td><td>Client Side</td><td>4 camera installation done 2 old reinstall and 2 new camera dvr side cabling not complete</td><td></td></tr><tr><td>06-02-2021 09:49:36</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr><tr><td>05-02-2021 12:48:58</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr><tr><td>05-02-2021 12:44:33</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	05-03-2021 09:54:45	YogeshDesai	New		-	09-02-2021 06:46:39	YogeshDesai	New		-	06-02-2021 03:55:37	YogeshDesai	Client Side	4 camera installation done 2 old reinstall and 2 new camera dvr side cabling not complete		06-02-2021 09:49:36	YogeshDesai	New		-	05-02-2021 12:48:58	YogeshDesai	New		-	05-02-2021 12:44:33	YogeshDesai	New		-
Date Time	Technician Name	Status	Remark	Sign																																				
05-03-2021 09:54:45	YogeshDesai	New		-																																				
09-02-2021 06:46:39	YogeshDesai	New		-																																				
06-02-2021 03:55:37	YogeshDesai	Client Side	4 camera installation done 2 old reinstall and 2 new camera dvr side cabling not complete																																					
06-02-2021 09:49:36	YogeshDesai	New		-																																				
05-02-2021 12:48:58	YogeshDesai	New		-																																				
05-02-2021 12:44:33	YogeshDesai	New		-																																				
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>27-07-2023 03:28:07</td><td>Kalpesh SubhashGurav</td><td>DVR No.3 10th floor camera Faulty DVR no3 16 number port issue Lift camera issue Pending Required Lift technician DVR to lobby TV 100 meter CAT 6 cable Required Lobby access (identx) not working properly HDMI splitter 3 in1out Required. hdmi to rj 45 converter Required</td></tr><tr><td>16-05-2023 09:57:14</td><td>Atique Salmani</td><td>Ther is wire cut by mouse so rejoin 8 core wire and also covered by 25 mm flexible pipe and also reset date n time and add 1 security person finger .all completed.</td></tr></tbody></table>					Date Time	Technician Name	Remark	27-07-2023 03:28:07	Kalpesh SubhashGurav	DVR No.3 10th floor camera Faulty DVR no3 16 number port issue Lift camera issue Pending Required Lift technician DVR to lobby TV 100 meter CAT 6 cable Required Lobby access (identx) not working properly HDMI splitter 3 in1out Required. hdmi to rj 45 converter Required	16-05-2023 09:57:14	Atique Salmani	Ther is wire cut by mouse so rejoin 8 core wire and also covered by 25 mm flexible pipe and also reset date n time and add 1 security person finger .all completed.																										
Date Time	Technician Name	Remark																																						
27-07-2023 03:28:07	Kalpesh SubhashGurav	DVR No.3 10th floor camera Faulty DVR no3 16 number port issue Lift camera issue Pending Required Lift technician DVR to lobby TV 100 meter CAT 6 cable Required Lobby access (identx) not working properly HDMI splitter 3 in1out Required. hdmi to rj 45 converter Required																																						
16-05-2023 09:57:14	Atique Salmani	Ther is wire cut by mouse so rejoin 8 core wire and also covered by 25 mm flexible pipe and also reset date n time and add 1 security person finger .all completed.																																						