




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE460</b>																														
<b>Priority :</b>	Low																													
<b>Created By :</b>	Admin - Apurva Vajaria																													
<b>Complaint Mob. No. :</b>	8169144587																													
<b>Technician Name :</b>	Yasin Shaikh		<b>Technician Mobile :</b>	8689802313																										
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	27-09-2019 11:56:34																											
<b>Vendor Details :</b>																														
<b>Company Name/Client Name :</b>	Corporate Square Ghatkopar	<b>Customer's Mobile :</b>	8169144587	<b>Name :</b>	Rajendra Sir																									
<b>Address :</b>																														
Mumbai , , , 400076 , Maharashtra																														
<b>AMC Details :</b>																														
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																											
<b>Product Name :</b>	CCTV																													
<b>Complain :</b>	survey for cameras 1. cabling required till nayan sir s cabin of 3 cameras install in lobby 2. Check how many ports are available in DVR																													
<b>Technician Comment :</b>	09 camera angle setting done and one camera working ok and shifting one camera lift camera painting not come lift man																													
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																													
<b>Remark :</b>	09 camera angle setting done and one camera working ok and shifting one camera lift camera painting not come lift man																													
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>28-11-2019 12:53:09</td><td>YasinShaikh</td><td>Completed</td><td></td><td>-</td></tr><tr><td>03-10-2019 05:12:47</td><td>YasinShaikh</td><td>Client Side</td><td>09 camera angle setting done and one camera working ok and shifting one camera lift camera painting not come lift man</td><td></td></tr><tr><td>03-10-2019 12:19:51</td><td>YasinShaikh</td><td>New</td><td></td><td>-</td></tr><tr><td>27-09-2019 11:56:35</td><td>YasinShaikh</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	28-11-2019 12:53:09	YasinShaikh	Completed		-	03-10-2019 05:12:47	YasinShaikh	Client Side	09 camera angle setting done and one camera working ok and shifting one camera lift camera painting not come lift man		03-10-2019 12:19:51	YasinShaikh	New		-	27-09-2019 11:56:35	YasinShaikh	New		-
Date Time	Technician Name	Status	Remark	Sign																										
28-11-2019 12:53:09	YasinShaikh	Completed		-																										
03-10-2019 05:12:47	YasinShaikh	Client Side	09 camera angle setting done and one camera working ok and shifting one camera lift camera painting not come lift man																											
03-10-2019 12:19:51	YasinShaikh	New		-																										
27-09-2019 11:56:35	YasinShaikh	New		-																										
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>27-07-2023 03:28:07</td><td>Kalpesh SubhashGurav</td><td>DVR No.3 10th floor camera Faulty DVR no3 16 number port issue Lift camera issue Pending Required Lift technician DVR to lobby TV 100 meter CAT 6 cable Required Lobby access (identx) not working properly HDMI splitter 3 in1out Required. hdmi to rj 45 converter Required</td></tr><tr><td>16-05-2023 09:57:14</td><td>Atique Salmani</td><td>Ther is wire cut by mouse so rejoint 8 core wire and also covered by 25 mm flexible pipe and also reset date n time and add 1 security person finger .all completed.</td></tr></tbody></table>					Date Time	Technician Name	Remark	27-07-2023 03:28:07	Kalpesh SubhashGurav	DVR No.3 10th floor camera Faulty DVR no3 16 number port issue Lift camera issue Pending Required Lift technician DVR to lobby TV 100 meter CAT 6 cable Required Lobby access (identx) not working properly HDMI splitter 3 in1out Required. hdmi to rj 45 converter Required	16-05-2023 09:57:14	Atique Salmani	Ther is wire cut by mouse so rejoint 8 core wire and also covered by 25 mm flexible pipe and also reset date n time and add 1 security person finger .all completed.																
Date Time	Technician Name	Remark																												
27-07-2023 03:28:07	Kalpesh SubhashGurav	DVR No.3 10th floor camera Faulty DVR no3 16 number port issue Lift camera issue Pending Required Lift technician DVR to lobby TV 100 meter CAT 6 cable Required Lobby access (identx) not working properly HDMI splitter 3 in1out Required. hdmi to rj 45 converter Required																												
16-05-2023 09:57:14	Atique Salmani	Ther is wire cut by mouse so rejoint 8 core wire and also covered by 25 mm flexible pipe and also reset date n time and add 1 security person finger .all completed.																												