

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE7346															
Priority :	Low														
Created By :	Admin - Apurva Vajaria														
Complaint Mob. No. :	8169144587														
Technician Name :	Prashant Nikalje		Technician Mobile :	9664609225											
Ticket Type :	Complain	Date & Time :	12-01-2023 11:24:23												
Vendor Details :															
Company Name/Client Name :	Corporate Square Ghatkopar	Customer's Mobile :	8169144587	Name :	Rajendra Sir										
Address :															
Mumbai , , , 400076 , Maharashtra															
AMC Details :															
Expiry Date :	01-01-1970 05:30:00		Type :												
Product Name :	CCTV														
Complain :	want to see online in tV so need to do survey														
Technician Comment :															
Complain Operator :	Desktop - Apurva Vajaria														
Remark :															
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>13-01-2023 02:46:51</td><td>Prashant Nikalje</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	13-01-2023 02:46:51	Prashant Nikalje	New		-
Date Time	Technician Name	Status	Remark	Sign											
13-01-2023 02:46:51	Prashant Nikalje	New		-											
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>27-07-2023 03:28:07</td><td>Kalpesh SubhashGurav</td><td>DVR No.3 10th floor camera Faulty DVR no3 16 number port issue Lift camera issue Pending Required Lift technician DVR to lobby TV 100 meter CAT 6 cable Required Lobby access (identx) not working properly HDMI splitter 3 in1out Required. hdmi to rj 45 converter Required</td></tr><tr><td>16-05-2023 09:57:14</td><td>Atique Salmani</td><td>Ther is wire cut by mouse so rejoint 8 core wire and also covered by 25 mm flexible pipe and also reset date n time and add 1 security person finger .all completed.</td></tr></tbody></table>					Date Time	Technician Name	Remark	27-07-2023 03:28:07	Kalpesh SubhashGurav	DVR No.3 10th floor camera Faulty DVR no3 16 number port issue Lift camera issue Pending Required Lift technician DVR to lobby TV 100 meter CAT 6 cable Required Lobby access (identx) not working properly HDMI splitter 3 in1out Required. hdmi to rj 45 converter Required	16-05-2023 09:57:14	Atique Salmani	Ther is wire cut by mouse so rejoint 8 core wire and also covered by 25 mm flexible pipe and also reset date n time and add 1 security person finger .all completed.	
Date Time	Technician Name	Remark													
27-07-2023 03:28:07	Kalpesh SubhashGurav	DVR No.3 10th floor camera Faulty DVR no3 16 number port issue Lift camera issue Pending Required Lift technician DVR to lobby TV 100 meter CAT 6 cable Required Lobby access (identx) not working properly HDMI splitter 3 in1out Required. hdmi to rj 45 converter Required													
16-05-2023 09:57:14	Atique Salmani	Ther is wire cut by mouse so rejoint 8 core wire and also covered by 25 mm flexible pipe and also reset date n time and add 1 security person finger .all completed.													