Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Details : VE9197							
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	8169144587						
Technician Name :	Yogesh Desai		Technicia:	an Mobile 8080922963			
Ticket Type :	Complain	Date & Time :	17-08-202	23 05:58:31			
Vendor Details :							
Company Name/Client Name:	Corporate Square Ghatkopar	Customer's Mobile :	81691445	587	Name :	Raje	endra Sir
Address:							
Mumbai , , , 4000	076 , Maharashtra						
AMC Details :							
Expiry Date :	01-01-1970 05:30:0	Type:					
Product Name:	CCTV						
Complain:	Standby DVR need to install						
Technician Comment :	Old DVR of 16 channel repaired and installed at A wing of co-operate square DVR working ok . Stand by DVR taken back to office . Also DVR no 3 is online can be viewed on ivms software. Work completed						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	Old DVR of 16 channel repaired and installed at A wing of co-operate square DVR working ok . Stand by DVR taken back to office . Also DVR no 3 is online can be viewed on ivms software. Work completed						
Status History :	Date Time	Technician Name	Status		Remark		Sign
	16-09-2023 08:02:24	YogeshDesai	Completed	and installed operate squa Stand by DV office . Also	6 channel repaire l at A wing of co- are DVR working o R taken back to DVR no 3 is online d on ivms software eted	k.	0/4/6/
	16-09-2023 03:45:27	YogeshDesai	New				-
	19-08-2023 11:42:40	YogeshDesai	New				-

Previou	S
Compla	in
History	:

Date Time	Technician Name	Remark		
27-07-2023 03:28:07	Kalpesh SubhashGurav	DVR No.3 10th floor camera Faulty DVR no3 16 number port issue Lift camera issue Pending Required Lift technician DVR to lobby TV 100 meter CAT 6 cable Required Lobby access (identx) not working properly HDMI splitter 3 in1out Required. hdmi to rj 45 converter Required		
16-05-2023 Atique Salmani 09:57:14		Ther is wire cut by mouse so rejoint 8 core wire and also coverd by 25 mm flexible pipe and also reset date n time and add 1 security person finger .all completed.		