Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Details : VE11408								
Priority:	Low							
Created By:	Admin - Apurva Vajaria							
Complaint Mob. No. :	9869439970							
Technician Name :	Neeraj Chauhan		Technician Mobile :	8898885764				
Ticket Type:	Complain	Date & Time :	18-04-2024 12:59:54					
Vendor Details :								
Company Name/Client Name :	Eden Garden	Customer's Mobile :	9869439970	Name :	Rajesh Sir			
Address:								
Mumbai , , , , Ma	harashtra							
AMC Details:								
Expiry Date :	01-01-1970 05:30:00		Type:					
Product Name :	CCTV							
Complain:	D15 and D25 camera offline issue A-202 intercom issue							
Technician Comment :	1 ip dome camera installation done B wing 2nd floor work okk							
Complain Operator :	Desktop - Apurva Vajaria							
Remark:	1 ip dome camera installation done B wing 2nd floor work okk							

Status History						
Status History :	Date Time	Technician Name	Status	Remark	Sign	
	27-04-2024 05:53:00	Neeraj Chauhan	Completed	1 ip dome camera installation done B wing 2nd floor work okk	W	
	27-04-2024 05:21:23	Neeraj Chauhan	New		-	
	20-04-2024 11:51:49	Neeraj Chauhan	Work Pending	a wing 201 intercom ok working done already and a 601 intercom punching crown side and duct with flat in side and b wing D 25 CMAERA ok working done and 2nd floor cmaera remove and take to office check (bcz seconds floor flat 202 owner carpenter work progress and cmaera remove to flat owner side then reinstall but cnaera not working)	4164	
	20-04-2024 10:29:33	Neeraj Chauhan	New		-	
	19-04-2024 04:54:19	Neeraj Chauhan	New		-	
	19-04-2024 10:10:03	Neeraj Chauhan	New		-	
Previous Complain History :	Date Time	Technician Name		Remark		
	23-04-2024 12:43:05	Atique Salmani	Camera can ir	Camera can installed same location but after work.		
	13-04-2024 01:20:48	Atique Salmani	B 701 new phone installed working ok A 201 cancel and a 601 renew painding client side becz cable missing new cabling from 2 nd floor to inside flate and d25 allready working.			