

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE13021																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9820007487																								
Technician Name :	Chandan Yadav		Technician Mobile :	9833262842																					
Ticket Type :	Complain	Date & Time :	17-10-2024 11:27:35																						
Vendor Details :																									
Company Name/Client Name :	Shanti Apt	Customer's Mobile :	9820007487	Name :	Rajesh Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	CCTV																								
Complain :	C wing lift plug point ready camera need to start																								
Technician Comment :	C wing lift camera working ok.but switch board fitting pending,switch board problem																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	C wing lift camera working ok.but switch board fitting pending,switch board problem																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>24-10-2024 11:04:05</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>17-10-2024 12:13:03</td><td>ChandanYadav</td><td>Work Pending</td><td>C wing lift camera working ok.but switch board fitting pending,switch board problem</td><td></td></tr><tr><td>17-10-2024 11:27:44</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	24-10-2024 11:04:05	ChandanYadav	New		-	17-10-2024 12:13:03	ChandanYadav	Work Pending	C wing lift camera working ok.but switch board fitting pending,switch board problem		17-10-2024 11:27:44	ChandanYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																					
24-10-2024 11:04:05	ChandanYadav	New		-																					
17-10-2024 12:13:03	ChandanYadav	Work Pending	C wing lift camera working ok.but switch board fitting pending,switch board problem																						
17-10-2024 11:27:44	ChandanYadav	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>13-11-2024 03:16:20</td><td></td><td></td></tr><tr><td>07-11-2024 10:54:44</td><td>ManojPolekar</td><td>F wing ppm done, change the CMOS battery.one camera lift not working and chek the office.lock problem solve. Intercom ppm done. Office dvr ppm done.</td></tr></tbody></table>					Date Time	Technician Name	Remark	13-11-2024 03:16:20			07-11-2024 10:54:44	ManojPolekar	F wing ppm done, change the CMOS battery.one camera lift not working and chek the office.lock problem solve. Intercom ppm done. Office dvr ppm done.											
Date Time	Technician Name	Remark																							
13-11-2024 03:16:20																									
07-11-2024 10:54:44	ManojPolekar	F wing ppm done, change the CMOS battery.one camera lift not working and chek the office.lock problem solve. Intercom ppm done. Office dvr ppm done.																							