## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

E: valiablisecure@yan						
Service Status De	tails : VE13338					
Priority:	Low					
Created By:	Admin - Apurva Vajaria					
Complaint Mob.	9820007487					
Technician Name :	Pravin Jagade		Technician Mobile :		7262044153	
Ticket Type :	Complain	Date & Time :	23-11-2024 10:59:46			
Vendor Details :	-		•			
Company Name/Client Name :	Shanti Apt	Customer's Mobile :	9820007487		Name :	Rajesh Sir
Address :						
Mumbai , , , , Mal	narashtra					
AMC Details :						
Expiry Date :	01-01-1970 05:30:0	0	Type:			
<b>Product Name:</b>	CCTV					
Complain:	Shop side IP bullet repaired camera need to install 2)F wing lift dome repaired camera need to install					
Technician Comment :	Shop side camera switch in b wing duct has been lock and key not with the guard work pending					
Complain Operator :	Desktop - Apurva Vajaria					
Remark:	Shop side camera switch in b wing duct has been lock and key not with the guard work pending F wing lift camera installed on 28.11.2024					
Status History :	Date Time	Technician Name	Status		Remark	Sign
	02-12-2024 03:45:35	PravinJagade	Work Pending			-
	02-12-2024 03:45:12	PravinJagade	Completed			-
	29-11-2024 02:35:19	PravinJagade	Work Pending	b wing du	e camera switch in act has been lock oot with the guard ding	CAYAI
	29-11-2024 12:04:50	PravinJagade	New			-
	28-11-2024 01:08:53	PravinJagade	New			-
	23-11-2024 11:00:51	PravinJagade	New			-
Previous	Date Time	Technician Name	Remark			
Complain History :	02-12-2024 12:35:56	SantoshPathak	Vishal bhai visited on 03.12.2024 and tv issue resolved			
mistory:	02-12-2024 12:33:30	Samusiif amak	vishal bhai visited on 03.12.2024 and tv issue resolved reconnected the cable and tv start			
	29-11-2024 10:51:00	PravinJagade	F wing tv off issue resolve working done. A wing passage camera off issue resolved because power off. C wing and d wing lift camera angle setting done.biomatric machine proper working.			