

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE14341																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	9820007487																													
Technician Name :	Siddhesh Chavan		Technician Mobile :	8080922985																										
Ticket Type :	Complain	Date & Time :	22-03-2025 12:42:36																											
Vendor Details :																														
Company Name/Client Name :	Shanti Apt	Customer's Mobile :	9820007487	Name :	Rajesh Sir																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
Product Name :	CCTV																													
Complain :	All cameras off f wing																													
Technician Comment :	Forth floor dvr camera supply issue allcaneras are connected on one supply of 12 v 20 àmp of cp plus si the camera are off																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	Forth floor dvr camera supply issue allcaneras are connected on one supply of 12 v 20 àmp of cp plus si the camera are off																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>25-03-2025 04:16:01</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>22-03-2025 06:27:33</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>22-03-2025 01:43:13</td><td>Siddhesh Chavan</td><td>Work Pending</td><td>Forth floor dvr camera supply issue allcaneras are connected on one supply of 12 v 20 àmp of cp plus si the camera are off</td><td>Bdyan</td></tr><tr><td>22-03-2025 12:42:43</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	25-03-2025 04:16:01	Siddhesh Chavan	New		-	22-03-2025 06:27:33	Siddhesh Chavan	New		-	22-03-2025 01:43:13	Siddhesh Chavan	Work Pending	Forth floor dvr camera supply issue allcaneras are connected on one supply of 12 v 20 àmp of cp plus si the camera are off	Bdyan	22-03-2025 12:42:43	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																										
25-03-2025 04:16:01	Siddhesh Chavan	New		-																										
22-03-2025 06:27:33	Siddhesh Chavan	New		-																										
22-03-2025 01:43:13	Siddhesh Chavan	Work Pending	Forth floor dvr camera supply issue allcaneras are connected on one supply of 12 v 20 àmp of cp plus si the camera are off	Bdyan																										
22-03-2025 12:42:43	Siddhesh Chavan	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>08-04-2025 12:00:53</td><td>Atique Salmani</td><td></td></tr><tr><td>01-04-2025 10:49:43</td><td>Neeraj Chauhan</td><td>18 camera no video issue solved and 16 channel new power supply install and dvr Rack bew fan install 2 tv wiewing issue solved and HDMI spelter no work collect and send to office Dvr cmos battery slot issue</td></tr></tbody></table>					Date Time	Technician Name	Remark	08-04-2025 12:00:53	Atique Salmani		01-04-2025 10:49:43	Neeraj Chauhan	18 camera no video issue solved and 16 channel new power supply install and dvr Rack bew fan install 2 tv wiewing issue solved and HDMI spelter no work collect and send to office Dvr cmos battery slot issue																
Date Time	Technician Name	Remark																												
08-04-2025 12:00:53	Atique Salmani																													
01-04-2025 10:49:43	Neeraj Chauhan	18 camera no video issue solved and 16 channel new power supply install and dvr Rack bew fan install 2 tv wiewing issue solved and HDMI spelter no work collect and send to office Dvr cmos battery slot issue																												