Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

| Service Status Deta | ails : VE15058 | | | | | |
|----------------------------------|--|---------------------|--|--|--|------------|
| Priority: | Low | | | | | |
| Created By: | Admin - Apurva Vajaria | | | | | |
| Complaint Mob. | 9820007487 | | | | | |
| Technician Name | Siddhesh Chavan | | Technician Mobile 8080922 | | 8080922985 | |
| Ticket Type : | Complain | Date & Time : | 21-06-2025 10:54:28 | | | |
| Vendor Details : | | | | | | |
| Company Name/Client Name : | Shanti Apt | Customer's Mobile : | 9820007487 Nam | | Name : | Rajesh Sir |
| Address : | | | | | | |
| Mumbai , , , , Maha | arashtra | | | | | |
| AMC Details : | | | _ | | _ | |
| Expiry Date : | 01-01-1970 05:30: | 00 | Type: | | | |
| Product Name: | cCTV-Intercom | | | | | |
| Complain: | 1)B wing lift 1 camera off 2)flat no. 101 intercom issue | | | | | |
| Technician Comment : | B wing lift camera issue pending because need to arrange lift person F wing 101 flat door lock | | | | | |
| Complain Operator : | Desktop - Apurva Vajaria | | | | | |
| Remark: | B wing lift camera issue pending because need to arrange lift person F wing 101 flat door lock | | | | | |
| Status History : | Date Time | Technician Name | Status | | Remark | Sign |
| | 26-06-2025 10:27:53 | 3 Siddhesh Chavan | Work Pending | B wing lift camera issue pending because need to arrange lift person F wing 101 flat door lock | | Cold |
| | 26-06-2025 10:00:05 | Siddhesh Chavan | New | | | - |
| | 21-06-2025 11:25:45 | Siddhesh Chavan | Work Pending | person r camera | ercom pending not falt. The lift is closed, a lift will be needed | |
| | 21-06-2025 10:54:37 | 7 Siddhesh Chavan | New | | | - |
| Previous Complain History | Date Time | Technician Name | Remark | | | |
| | 16-07-2025 10:23:44 | 1 Neeraj Chauhan | B wing lift camera issue solved and cabling cutting rate cable joint to place camera working okk | | | |
| | | | A wing passage camera off issue resolved done. Work complete. | | | |